

PERIMETER INTRUSION DETECTION SYSTEM

USER MANUAL

STEP 1: Locate the USB port at the side of the device and plug it.

The power shall automatically come ON and the ultrasonic sensor will start to search for nearby object and the distance of the object is displayed in the LCD screen display as depicted below:



STEP 2: Bring your hand or any object such that the distance between the sensor and the object/hand is equals to or less than 10cm, by so doing, the buzzer and LED shall sounds and produces red blink respectively, and the LCD display “DETECTED!!!” as depicted below:

