Bilkent University

ENG 401

Technical Report Writing and Presentation

A Report to to Investigate and Produce Solutions to the Electricity

Waste in Bilkent Dormitory 78

Technical Report

Umut Mücahit Köksaldı 21402234 ENG 401 – 01

Submitted in Partial Fulfillment of the Requirements for ENG 401 Technical Report Writing and Presentation

Bilkent University
28, July, 2017
Department of Computer Engineering
Bilkent 06800 Ankara
TURKEY

Table of Contents

Introduction	1
Problem Definition	1
Human error and lack of control mechanisms	2
Out-of-date and worn-out lightbulbs	2
Unplanned installment of lighting fixtures	2
Proposed Solutions	3
Use of sensors to cut down on unnecessary up-time	3
Incorporating energy efficient lightbulbs	4
Optimizing the distribution of lightbulbs	4
Criteria for Assessing Solutions	5
Research Methodology	5
Results & Analysis	7
Analysis of the use of sensors	7
Cost-effectiveness of sensors	7
Acceptability of sensors	7
Feasibility of sensors	8
Analysis of installing LED lightbulbs	8
Cost-effectiveness of LED lightbulbs	8
Acceptability of LED lightbulbs	8
Feasibility of LED lightbulbs	9
Analysis of the optimization of lighting fixture layout	9
Cost-effectiveness of the lighting fixture optimization	9
Acceptability of the lighting fixture optimization	9
Feasibility of the lighting fixture optimization	10
Conclusion & Recommendations	10
References	11

Abstract

The aim of this project is to provide solutions to the electricity waste in Bilkent University Dormitory 78. To this end, three root causes were identified as the source of the problem and three corresponding solutions were developed to address these causes. These solutions were then further assessed with respect to a set of criteria. Interviews were conducted and calculations were made to properly evaluate the solutions. Of the three solutions, two of them were found appropriate to be integrated into the dormitory building based on the criteria. The most convenient solution was replacing the fluorescent lights inside the building with energy efficient LED lightbulbs. The second-best solution was integrating sensors into the lighting fixtures inside the dormitory building. The last and least fitting solutions was the optimization and rearrangement of the lighting fixtures in the building. A plan of action was devised consisting of the combination of the first two solutions: installing LED lightbulbs and implementing sensors into the lighting fixtures.

List of Figures and Tables

Figure 1. Lighting distribution inside Dormitory 78	:
Table 1. Research Methodology	: