## ASBESTOS REGISTER



SITE: 7733 Dyson 118 Mill Hill Road, Bondi Junction LAST UPDATED: 23/03/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Туре	Friable / Non-Friable	Quantity	Condition	Assessment / Action
19/04/2016	Exterior cladding	Asbestos cement sheet	Non-friable	2 sqm	Good/stable	Remove and dispose of the ACM as part of the contract works
19/04/2016	Eave soffit lining	Asbestos cement sheet	Non-friable	2.5 sqm	Good/stable	Remove and dispose of the ACM as part of the contract works
19/04/2016	Front porch	Asbestos cement sheet	Non-friable	Unknown	Good/stable	Protect and retain ACM from damage during the course of the works
19/04/2016	Kitchen	Asbestos cement sheet	Non-friable	9.8 sqm	Good/stable	Remove and dispose of the ACM as part of the contract works
19/04/2016	External laundry	Asbestos cement sheet	Non-friable	2.3 sqm	Good/stable	Remove and dispose of the ACM as part of the contract works
19/04/2016	Electrical meter board	Asbestos cement sheet	Non-friable	Unknown	Good/stable	Protect and retain ACM from damage during the course of the works