## ASBESTOS REGISTER



SITE: 7695 Glascott 12 The Chase Road, Turramurra LAST UPDATED: 13/06/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Туре	Friable / Non-Friable	Quantity	Condition	Assessment / Action
19/10/2016	Eave soffit lining	Asbestos cement sheet	Non-friable	13.55 sqm	Good/stable	Remove and dispose of the ACM as part of the contract works Removed 13/06/2017
19/10/2016	Gable end lining	Asbestos cement sheet	Non-friable	Unknown	Good/stable	Protect and retain the ACM from damage during the course of the works
19/10/2016	Front verandah	Asbestos cement sheet	Non-friable	Unknown	Good/stable	Protect and retain the ACM from damage during the course of the works
19/10/2016	Shower	Asbestos cement sheet	Non-friable	13.2 sqm	Good/stable	Remove and dispose of the ACM as part of the contract works Removed 13/06/2017
19/10/2016	WC	Asbestos cement sheet	Non-friable	4 sqm	Good/stable	Remove and dispose of the ACM as part of the contract works Removed 13/06/2017

## ASBESTOS REGISTER



19/10/2016	Hallway back	Asbestos cement	Non-friable	3 sqm	Good/stable	Remove and dispose of the ACM as	
		sheet				part of the contract works	
						Removed 13/06/2017	

WHS-5.1-0502— Asbestos Register

Issued: February 2017 Version: 1.0