ASBESTOS REGISTER



SITE: 7827 Willcock 78 Barons Crescent, Hunters Hill LAST UPDATED: 26/06/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Туре	Friable / Non-Friable	Quantity	Condition	Assessment / Action
22/06/2017	Eave soffit lining	Asbestos cement sheet	Non-friable	17 sqm	Good/Stable Some exposed edges to the rear section eaves Surface coated to the exposed areas	3.5 sqm to be removed by Cape Cod as part of the contract works. Protect the retained ACM from damage during the course of the works
22/06/2017	Patio soffit lining	Asbestos cement sheet	Non-friable	16.5 sqm	Good/Stable Surface coated to the exposed areas	To be completely removed by Cape Cod as part of the contract works
22/06/2017	Garage ceiling lining	Asbestos cement sheet	Non-friable	5 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
22/06/2017	Bathroom wall lining	Asbestos cement sheet	Non-friable	16 sqm	Good/Stable Surface coated to the exposed areas	To be completely removed by Cape Cod as part of the contract works

WHS-5.1-0502- Asbestos Register

Issued: February 2017

Version: 1.0

Page 1 of 2 Approved by: WHS & Human Resources Coordinator Printed: 26/06/2017 8:38 AM

ASBESTOS REGISTER



22/06/2017	Garage ceiling	Asbestos cement	Non-friable	2.25 sqm	Good/Stable	Protect the retained ACM from
	lining	sheet			Surface coated to the exposed areas	damage during the course of the works

WHS-5.1-0502— Asbestos Register

Issued: February 2017 Version: 1.0