

6 Premier Drive, Albion Park NSW 2527 Telephone: 02 4257 4770 Mobile No: (Mark) 0417 064 161

(John) 0418 471 343

Email: jonspin@bigpond.com.au

HAZARDOUS MATERIALS ASSESSMENT REPORT

Client: Cape Cod Australia Pty. Limited

Job details: Owner: Ms. J. Park & Mr. S. Warner.

Location: 53 Gipps Street, Paddington.

Plans for Job No: 7752/15 Revision No: G Dated: 05-12-2016

Council area: WOOLLAHRA

Date of assessment: 12th January 2017

Our reference: HM05380117

The Client acknowledges that:

This report is provided for **the exclusive information of the Client**. It is a term and condition of the terms upon which this report is provided, that if the Client chooses to rely upon the report, that the Company and the Person making this report will not be liable to the Client or to any other Person who suffers personal or property damage or financial loss in respect of any cause of action or tort, contract or however the cause of action is said to price

This report is **not a guarantee or warranty** or an all-encompassing report dealing with the above property from every aspect. It is based on the condition of the property and the "**Readily Accessible Areas**" at the time of assessment. It is a reasonable attempt to identify as far as *reasonably practicable*, any significant hazardous materials i.e. materials "that may" contain asbestos [ACM] or [ACD], ceiling dusts "that may" contain lead, paints "that may" contain lead or synthetic mineral fibres [SMF], **visible** at the time of assessment.

This report, based on visual assessment, will not disclose hazardous materials in inaccessible areas, not readily accessible or obstructed at the time of assessment. Areas which are not normally accessible were not assessed and include but are not limited to – inside walls, the interior of a flat roof or beneath a suspended floor filled with earth.

This report is **not a Certificate of Compliance** with the requirements of the WHS Act 2011 and WHS Regulations 2011, relevant Codes of Practice or Australian Standards or NSW Office of Environment and Heritage [OEH] Regulations.



Front north eastern elevation of the residence

1. GENERAL DESCRIPTION OF THE EXISTING RESIDENCE

Estimated age:	Circa 1870 – 1880.
Type of construction:	Double storey full brick / brick cavity construction built on sandstone block footings supporting a suspended timber floor system.
External cladding:	Combination of rendered clay masonry brickwork and timber weatherboard cladding.
Roof:	Gable ended hip and valley roof structure with concrete roofing tiles.

Occupancy Status: Was the residence occupied at the time of assessment?

Yes	✓	No		Not Applicable	
-----	---	----	--	----------------	--

Orientation: For the purpose of this report the front of the residence faces:

East		West		North		South		Northeast	✓	Northwest		Southeast		Southwest		
------	--	------	--	-------	--	-------	--	-----------	---	-----------	--	-----------	--	-----------	--	--

2. AREAS ASSESSED

This assessment covers the following "Readily Accessible Areas" of the existing residence layout to identify as far as reasonably practicable any significant hazardous materials i.e. materials "that may" contain asbestos [ACM] or [ACD], ceiling dusts "that may" contain lead, paints "that may" contain lead or synthetic mineral fibre insulation [SMF].

Under Floor x Exterior ✓ Roof Surfaces ✓ Roof Cavity ✓ Interior ✓ Car	N/A	Roof Cavity / Interior / Carport N	✓	Roof Surfaces	✓	Exterior		
---	-----	------------------------------------	---	---------------	---	----------	--	--

3. ASSESSMENT OF THE EXISTING RESIDENCE LAYOUT FOR HAZARDOUS MATERIALS

Area Assessed	Description and Comment	Assessment / Action
Under Floor Space	We were unable to access the under-floor space due to construction methods.	No action is required.
Exterior		
Cladding	Combination of rendered clay masonry brickwork and timber weatherboard cladding. Note 1: existing Kitchen, Bedroom 4 and Upstairs hallway to be demolished as part of the proposed Contract works.	Appropriate dust suppression measures to be provided. No further action is required.
	Note 2 : existing Living room, Lobby and Bedroom 4 windows to be closed in as part of the proposed Contract works.	
Eave soffit lining	Possible asbestos cement [ACM] sheet to rear elevation eave soffits.	~ 3.5 m ²
	Note: rear eave soffit removed to accommodate the first-floor extension as part of the proposed Contract works.	Remove and dispose of the ACM sheet as required in a manner approved by Safe Work NSW, NSW OEH and Woollhara Council.
		See attached Safe Work Method Statement for the removal of material <i>that may</i> contain asbestos [ACM].
		All necessary steps are to be taken to protect the retained asbestos cement [ACM] sheet from damage during the course of the works.
		Appropriate dust suppression measures to be provided.
		No further action is required
Gable end lining	Combination of rendered clay masonry brickwork and timber weatherboard cladding. Note: Rear south west elevation to be demolished as part of the proposed Contract works.	Appropriate dust suppression measures to be provided. No further action is required.
Roofing material	Concrete roofing tiles. Note: Approximately 50% of the concrete roofing tiles to be removed as part of the proposed Contract works.	Remove and dispose of the concrete roof tiles in a manner approved by NSW OEH and Woollhara Council. Appropriate dust suppression measures to be provided. No further action is required.

Area Assessed	Description and Comment	Assessment / Action
Front Porch	Suspended sandstone slate lined concrete slab floor supporting a timber framed balcony with possible asbestos cement [ACM] sheet to the soffit lining. Note: existing balcony and support posts to be removed and replaced as part of the proposed Contract works.	~ 5.0 m² Remove and dispose of the ACM sheet as required in a manner approved by Safe Work NSW, NSW OEH and Woollhara Council. See attached Safe Work Method Statement for the removal of material that may contain asbestos [ACM]. Appropriate dust suppression measures to be provided. No further action is required.
Rear Pergola	Attached timber framed structure with no roof and terracotta tiled floor. Note: existing pergola balcony to be removed to accommodate Kitchen extension as part of the proposed Contract works.	Appropriate dust suppression measures to be provided. No further action is required.
Front balcony	Timber framed structure and decking with timber balustrade and handrail. Pre-finished corrugated profile sheet metal roofing. Note: existing balcony to be removed and replaced as part of the proposed Contract works.	Appropriate dust suppression measures to be provided. No further action is required.
Side balcony	Timber framed structure and decking with timber balustrade and handrail. Note: existing balcony to be removed to accommodate the first-floor additions as part of the proposed Contract works.	Appropriate dust suppression measures to be provided. No further action is required.
Painting - general	Combination of oil based and acrylic based surface coating to the timber windows, gable ends, eaves and trims. No exposed lead based paints were observed.	Appropriate dust suppression measures to be provided. No further action is required.
Interior Ground Flo	or	
Entry	Painted cement rendered walls. Plaster ceiling with cove profiled plaster cornice. Note: existing front door and furniture to be removed and replaced as part of the proposed Contract works.	Appropriate dust suppression measures to be provided. No further action is required.

Area Assessed	Description and Comment	Assessment / Action
Front alcove Note: electrical meter board	Combination painted cement rendered walls and painted brickwork. Possible asbestos cement [ACM] sheet to the ceiling lining. Note: existing opening (gate) to be bricked up as part of the proposed Contract works.	Appropriate dust suppression measures to be provided. No further action is required.
Powder Room Note: shown as Store on Construction Drawing 3 of 8 for Job No. 7752/15.	Painted cement rendered walls and plaster ceiling. Note: existing plumbing and drainage services to be terminated as part of the proposed Contract works.	Appropriate dust suppression measures to be provided. No further action is required.
Store Note: shown as Powder room on Construction Drawing 3 of 8 for Job No. 7752/15.	Combination painted cement rendered and possible asbestos cement [ACM] sheet to the walls. Possible asbestos cement [ACM] sheet to the ceiling lining with timber mould cornice. Note: existing store room to be stripped to accommodate Powder Room as part of the proposed Contract works.	Remove and dispose of the ACM sheet as required in a manner approved by Safe Work NSW, NSW OEH and Woollhara Council. See attached Safe Work Method Statement for the removal of material that may contain asbestos [ACM]. All necessary steps are to be taken to protect the retained asbestos cement [ACM] sheet from damage during the course of the works. Appropriate dust suppression measures to be provided. No further action is required.
Lounge Note: fireplace	Combination painted cement rendered and plasterboard walls. Plaster ceiling with plaster cornice. Note 1: Possible asbestos cement [ACM] sheet to the under-stairs lining to be retained as part of the proposed Contract works. Note 2: existing door opening to Living room to be modified as part of the proposed Contract works. Contract works.	All necessary steps are to be taken to protect the retained asbestos cement [ACM] sheet from damage during the course of the works. Appropriate dust suppression measures to be provided. No further action is required.

Area Assessed	Description and Comment	Assessment / Action
Living	Plasterboard walls. Plasterboard ceiling with cove profiled plaster cornice. Note 1: existing door opening to Lounge room to be modified as part of the proposed Contract works. Note 2: existing window opening to be closed in as part of the proposed Contract works. Note 3: existing floor tiles to be removed, new floor boards laid and ceilings replaced as part of the proposed Contract works.	Appropriate dust suppression measures to be provided. No further action is required.
Kitchen	Plasterboard walls, tiled to splashback level. Plasterboard ceiling with cove profiled plaster cornice. Note 1: existing Kitchen services to be terminated as part of the proposed Contract works. Note 2: existing Kitchen cupboards to be removed as part of the proposed Contract works. Note 3: existing floor tiles to be removed, new floor boards laid and ceilings replaced as part of the proposed Contract works.	Appropriate dust suppression measures to be provided. No further action is required.
Pantry	Combination painted cement rendered and plasterboard walls. Possible asbestos cement [ACM] sheet to the ceiling lining. Note: existing floor tiles to be removed, new floor boards laid and ceilings replaced as part of the proposed Contract works.	Remove and dispose of the ACM sheet as required in a manner approved by Safe Work NSW, NSW OEH and Woollhara Council. See attached Safe Work Method Statement for the removal of material that may contain asbestos [ACM]. All necessary steps are to be taken to protect the retained asbestos cement [ACM] sheet from damage during the course of the works. Appropriate dust suppression measures to be provided. No further action is required.

Area Assessed	Description and Comment	Assessment / Action
Laundry	Painted cement rendered.	~ 2.25 m²
	Possible asbestos cement [ACM] sheet to the ceiling lining. Note: existing slab floor to be removed and replaced as part of the proposed Contract works.	Remove and dispose of the ACM sheet as required in a manner approved by Safe Work NSW, NSW OEH and Woollhara Council.
		See attached Safe Work Method Statement for the removal of material <i>that may</i> contain asbestos [ACM].
		All necessary steps are to be taken to protect the retained asbestos cement [ACM] sheet from damage during the course of the works.
		Appropriate dust suppression measures to be provided.
		No further action is required.
Stairwell	Plasterboard walls. Plaster ceiling with cove profiled plaster	Appropriate dust suppression measures to be provided.
	cornice. Note: not associated with the proposed Contract works.	No further action is required.
Painting - general	Combination of oil based and acrylic based surface coating to ceilings, walls, doors, timber windows and trims.	Appropriate dust suppression measures to be provided. No further action is required.
	No exposed lead based paints were observed.	
Interior First Floor		
Note: attic ladder	Plasterboard walls. Plaster ceiling with cove profiled plaster cornice. Note: existing attic ladder to be replaced as part of the proposed Contract works.	Appropriate dust suppression measures to be provided. No further action is required.
Shower	Possible asbestos cement [ACM] sheet to the walls, tiled floor to ceiling. Plasterboard ceiling with cove profiled plaster cornice. Note: existing services and linings to be replaced as part of the proposed Contract works.	All necessary steps are to be taken to protect the retained asbestos cement [ACM] sheet from damage during the course of the works. Appropriate dust suppression measures to be provided. No further action is required.

Area Assessed	Description and Comment	Assessment / Action
Bedroom 3 Note: fireplace	Combination painted cement rendered and plasterboard walls. Plasterboard ceiling with cove profiled plaster cornice. Note: existing door and architraves to be replaced as part of the proposed Contract works.	Appropriate dust suppression measures to be provided. No further action is required.
Bedroom 2	Combination painted cement rendered and plasterboard walls. Plasterboard ceiling with cove profiled plaster cornice. Note: existing door and architraves to be replaced as part of the proposed Contract works.	Appropriate dust suppression measures to be provided. No further action is required.
Bedroom 4	Combination painted cement rendered and plasterboard walls. Plasterboard ceiling with cove profiled plaster cornice. Note: not associated with the proposed Contract works.	Appropriate dust suppression measures to be provided. No further action is required.
Bedroom 1 Note: shown as Walk in Robe on Construction Drawing 3 of 8 for Job No. 7752/15. Note 2: Raked ceiling	Plasterboard walls. Plasterboard ceiling with square set wall / ceiling junction. Note: existing Bedroom to become WIR and Ensuite as part of the proposed Contract works.	Appropriate dust suppression measures to be provided. No further action is required.
Ensuite Note: Raked ceiling	Painted cement rendered walls, tiled to 2.1m. Plasterboard ceiling with square set wall / ceiling junction. Note: existing services and linings to be replaced as part of the proposed Contract works.	Appropriate dust suppression measures to be provided. No further action is required.
Painting - general	Combination of oil based and acrylic based surface coating to ceilings, walls, doors, timber windows and trims. No exposed lead based paints were observed.	Appropriate dust suppression measures to be provided. No further action is required.

Area Assessed	Description and Comment	Assessment / Action
Pitched Roof Cavity	Traditional cut and pitched timber roof structure Note 1: No sarking is provided to the underside of the concrete roof tiles or sheet metal roofing. Note 2: no insulation was observed to the roof space. Note 3: Approximately 50% of the roof surface to be removed as part of the proposed Contract works. Note 4: some household materials stored in the roof space.	In our opinion the air quality will not generally be affected during the course of the construction of the new first floor addition. Remove and dispose of the sheet metal roofing in a manner approved by NSW OEH and Woollhara Council. Appropriate dust suppression measures to be provided. No further action is required.
Attic	Particleboard flooring with hardboard/Masonite lined walls. Note: existing attic to be demolished and reconstructed as part of the proposed Contract works.	Appropriate dust suppression measures to be provided. No further action is required.
Electrical Meter Board	Located on the front verandah alcove wall of the residence. No hazardous materials noted. Note: meter board and POA to be relocated as part of the proposed Contract works.	Appropriate dust suppression measures to be provided. No further action is required.
	of materials " <i>that may</i> " contain asbestos ed as part of the proposed Contract works.	16.25 m ²

SITE ASBESTOS [ACM] REGISTER

Location of ACM	Туре	Quantity	Condition	Assessment / Action
Eave soffit lining	Possible asbestos cement sheet	~ 3.5 m ²	Non-Friable Good / Stable Painted	To be removed by Cape Cod as part of Contract works. Protect the retained ACM from damage during the course of the works.
Front Porch / Balcony soffit lining	Possible asbestos cement sheet	~ 5.0 m ²	Non-Friable Good / Stable Painted	To be removed by Cape Cod as part of Contract works.
Front Alcove ceiling lining	Possible asbestos cement sheet	~ 1.0 m ²	Non-Friable Good / Stable Painted	Protect the retained ACM from damage during the course of the works.
Store wall and ceiling lining	Possible asbestos cement sheet	~ 4.0 m ²	Non-Friable Good / Stable Painted	To be removed by Cape Cod as part of Contract works.
Laundry ceiling lining	Possible asbestos cement sheet	~ 2.25 m ²	Non-Friable Good / Stable Painted	To be removed by Cape Cod as part of Contract works.
Under staircase lining	Possible asbestos cement sheet	~ 2.0 m ²	Non-Friable Good / Stable Painted	Protect the retained ACM from damage during the course of the works.

DEMOLITION WORK PLAN

The partial demolition of the residence and the removal, storage, handling and disposal of building materials must be carried out as far as *reasonably practicable* in accordance with the following Regulations;

- Work Health and Safety Act 2011 and Work Health and Safety Regulations 2011
- Safe Work NSW Code of Practice How to manage and control asbestos in the workplace
- Safe Work Australia Code of Practice How to safely remove asbestos
- NSW Work Health and Safety Regulation 2011 Chapter 4 Hazardous Work
- NSW Work Health and Safety Regulation 2011 Chapter 6 Construction Work
- NSW Work Health and Safety Regulation 2011 Chapter 7 Hazardous Chemicals
- NSW Work Health and Safety Regulation 2011 Chapter 8 Asbestos
- Australian Standard AS2601 [2001] Demolition of Structures
- NSW Protection of the Environment Operations Act [1997] or as amended
- NSW Protection of the Environment Operations [Waste] Regulation [2014]
- NSW Office of Environment and Heritage [OEH] Regulations and Guidelines

A Demolition Work Plan must be submitted to WOOLLAHRA MUNICIPAL Council and the Principal Certifying Authority (PCA) if WOOLLAHRA MUNICIPAL Council is not the PCA, not less than five [5] working days **before commencing any demolition works** involving products or materials "that may" contain asbestos [ACM].

A copy of the Demolition Work Plan must be maintained on site and be made readily accessible to the Council Officer or 'workers' upon request.

ASBESTOS [ACM] REMOVAL CONTROL PLAN

Safe Work Method Statement - Removal & Disposal of Materials that may contain Asbestos

Any work involving the demolition, storage and disposal of products or materials "that may" contain asbestos [ACM] must be carried out as far as is reasonably practicable to minimise the release of airborne asbestos dust and fibres [ACD] in accordance with the following requirements;

- Relevant Work Health and Safety legislation including but not limited to; Work Health and Safety Regulation 2011 Chapter 8 Asbestos; Safe Work NSW Code of Practice How to manage and control asbestos in the workplace; Safe Work Australia Code of Practice How to safely remove asbestos and NSW Office of Environment and Heritage [OEH] requirements.
- WOOLLAHRA MUNICIPAL Council Demolition Report as adopted 21 October 2004
- The person with Management Control of the workplace and the licensed Asbestos Removalist must, so far as is reasonably practicable, and before commencing the asbestos [ACM] removal work, consult with and inform the following people about the asbestos [ACM] removal work and when the work will commence, so as to eliminate or minimise the exposure of the risks associated with asbestos:
 - The person who commissioned the asbestos removal work [Site Management]
 - A person conducting a business or undertaking at the workplace [Contractors]
 - The occupants of the domestic premises [Owner or Tenant]

- Anyone occupying premises in the immediate vicinity of the workplace [Neighbours]
- All work procedures are to be devised as far as is reasonably practicable, to minimise the release of dust and fibres [ACD].
- Appropriate warning signage and barricades are to be erected to prevent as far as is reasonably practicable, entry of anyone not connected with the removal activity into the work area.
- The sign must be clearly displayed in a prominent visible position at the front of the site; containing the words "DANGER ASBESTOS REMOVAL IN PROGRESS" and including the details of the licensed Asbestos Removal Contractor [PCBU].
- When working with products and materials "that may" contain asbestos [ACM] all 'workers' are to wear personal protective equipment [PPE] including coveralls and approved respiratory protective equipment [RPE] in accordance with the requirements of AS/NZS1716 Respiratory Protection devices and AS/NZS1715- Selection, use and maintenance of respiratory protective devices.
- As far as is reasonably practicable, use non powered hand tools for the removal of the materials that may contain asbestos [ACM] as these generate much less dust [ACD]. Do not use abrasive cutters and sanders, scrub or water blast the surface of products and materials "that may" contain asbestos [ACM].
- All products and materials "that may" contain asbestos [ACM] are to be kept damp to minimise
 as far as is reasonably practicable the generation of airborne asbestos dust and fibres [ACD].
 Prevent and or contain excess run off water.
- Where it is reasonably practicable work in well ventilated areas.
- Use drop sheets to collect debris of materials that may contain asbestos [ACM]. Dispose of smaller products and materials "that may" contain asbestos [ACM] pieces and collected dust [ACD] in recommended heavy duty plastic bags which are clearly labelled "asbestos waste".
- Wet clean or use approved vacuum cleaning equipment [HEPA] which complies with AS/NZS 603335.2.69 Industrial vacuum cleaners. Household vacuum cleaners must never be used where asbestos [ACM] or [ACD] is or may be present, even if the unit has a HEPA filter.
- Wall cladding and ceiling lining sheets "that may" contain asbestos [ACM] are not to be reused.
- All products and materials "that may" contain asbestos [ACM] or [ACD] are to be stored, transported and disposed of in accordance with the NSW Protection of the Environment Operations Act [1997 or as amended] and NSW Protection of the Environment Operations [Waste] Regulation [2014]
- All products and materials "that may" contain asbestos [ACM] or [ACD] is to be either wrapped
 in recommended heavy duty plastic sheeting or placed in leak proof lined bins or vehicles and
 appropriately covered and sealed.
- All products and materials "that may" contain asbestos [ACM] or [ACD] are to be stored in a secure area and removed from site as soon as is reasonably practicable in a covered leak proof vehicle.
- A Clearance Certificate of Statement, prepared by a suitably competent person i.e. an Occupational Hygienist, Safe Work NSW licensed Asbestos Removalist, licensed Asbestos Assessor or a "competent person" must be provided to Council upon completion of the works prior to an Occupation Certificate being issued, which confirms that the material "that may"

contain asbestos [ACM] or [ACD] has been removed appropriately and the relevant Conditions of Consent have been satisfied.

 All products and materials "that may" contain asbestos [ACM] or [ACD] are to be disposed of as soon as is reasonably practicable, at a licensed asbestos disposal site and in a manner approved by Safe Work NSW, NSW Office of Environment and Heritage [OEH] or WOOLLAHRA MUNICIPAL Council.

Safe Work Method Statement - Removal and Disposal of Ceiling Dust that may contain Lead

All Contractors [PCBU] and 'workers' involved in the cleaning, repairing or replacement of ceilings are to follow the following procedures in order to minimise as far as is reasonably practicable, health risks from the ceiling dust. These procedures include but are not limited to:

- Appropriate warning signage and barricades are to be erected to prevent as far as is reasonably practicable, entry of anyone not connected with the removal activity into the work area.
- When working with in ceiling voids containing ceiling dust all 'workers' are to wear personal protective equipment [PPE] including coveralls and approved respiratory protective equipment [RPE] in accordance with the requirements of AS/NZS1716 Respiratory Protection devices and AS/NZS1715 Selection, use and maintenance of respiratory protective devices. Eye protection, complying with AS/NZS1336 and AS/NZS1337 whenever full face respirators are not used
- Ceiling voids are to be cleaned of accumulated dust before commencing any work involving partial or complete removal of the ceiling sheets.
- The property Owner [Client] is to be advised to clear or cover personal effects in adjoining living spaces as far as is *reasonably practicable*.
- Any openings between living areas are to be sealed prior to the commencement of any removal work of ceiling dust "that may" contain lead to prevent as far as is reasonably practicable, dust entering the retained living areas.
- Use approved vacuum cleaning equipment [HEPA] which complies with AS/NZS 603335.2.69
 Industrial vacuum cleaners, to prevent the release as far as is reasonably practicable, of dust that may contain lead while it is being removed. Do not use household vacuum cleaners even if the unit has a HEPA filter.
- Dispose of the collected dust in approved plastic bags which are clearly labelled.
- All ceiling dust containing lead or other contaminants is to be disposed of as far as is reasonably practicable in a manner, and at as site, approved by the Safe Work NSW, NSW Office of Environment and Heritage [OEH], appropriate disposal Authority or WOOLLAHRA MUNICIPAL Council.
- To minimise as far as is reasonably practicable contamination of living areas of the residence, airless spraying of PVA to seal the cleaned surfaces is recommended whenever the ceiling is removed.

<u>Safe Work Method Statement – Removal and Disposal of Synthetic Mineral Fibre Insulation</u>

All Contractors [PCBU's] and 'workers' involved in the removal of suspected synthetic mineral fibre [SMF] insulation are to follow the following procedures in order to minimise as far as is reasonably practicable health risks from synthetic mineral fibre [SMF] insulation. These procedures include but are not limited to:

- Appropriate warning signage and barricades are to be erected to prevent as far as is reasonably practicable, entry of anyone not connected with the removal activity into the work area.
- When removing synthetic mineral fibre [SMF] insulation all 'workers' are to wear personal protective equipment [PPE] including coveralls and an approved respiratory protective equipment [RPE] in accordance with the requirements of AS/NZS1716 Respiratory Protection devices and AS/NZS1715 Selection, use and maintenance of respiratory protective devices. Eye protection, complying with AS/NZS1336 and AS/NZS1337 whenever full face respirators are not used.
- The property Owner [Client] is to be advised to clear or cover personal effects in adjoining living spaces as far as is reasonably practicable.
- Any openings between living areas are to be sealed prior to the commencement of any removal work of synthetic mineral fibre [SMF] insulation to prevent as far as is reasonably practicable, dust and fibres entering the retained living areas.
- Use approved vacuum cleaning equipment that complies with AS/NZS 603335.2.69 Industrial vacuum cleaners, to prevent as far as is reasonably practicable, the release of dust "that may" contain synthetic mineral fibres [SMF] while it is being removed. Do not use household vacuum cleaners even if the unit has a HEPA filter.
- Dispose of the synthetic mineral fibre [SMF] insulation in sealed approved plastic bags which are clearly labelled.
- All synthetic mineral fibre [SMF] insulation or other contaminants is to be disposed of as far as
 is reasonably practicable, in a manner, and at a site, approved by Safe Work NSW, NSW
 Office of Environment and Heritage [OEH], appropriate licensed disposal Authority or
 WOOLLAHRA MUNICIPAL Council.

Safe Work Method Statement - Lead based Paints

All Contractors [PCBU's] and 'workers' involved in the cleaning, repairing or replacement of suspected lead based paint are to follow the following procedures in order to minimise as far as is reasonably practicable, health risks from lead based paints. These procedures include but are not limited to:

- Appropriate warning signage and barricades are to be erected to prevent as far as is reasonably practicable, entry of anyone not connected with the removal activity into the work area.
- When working with lead based paints all 'workers' are to wear personal protective equipment [PPE] including coveralls and an approved respiratory protective equipment [RPE] in accordance with the requirements of AS/NZS1716 Respiratory Protection devices and AS/NZS1715 Selection, use and maintenance of respiratory protective devices. Eye protection, complying with AS/NZS1336 and AS/NZS1337 whenever full face respirators are not used.
- The property Owner [Client] is to be advised to clear or cover personal effects in adjoining living spaces as much as is practical.
- Any openings between living areas are to be sealed prior to the commencement of any removal work of lead based paints to prevent as far as is reasonably practicable, dust entering the retained living areas.
- Use approved vacuum cleaning equipment [HEPA] which complies with AS/NZS 603335.2.69
 Industrial vacuum cleaners, to prevent as far as is reasonably practicable, the release of dust

that may contain lead while it is being removed. **Do not use** household vacuum cleaners even if the unit has a HEPA filter.

- Dispose of collected lead based paint dust in sealed approved plastic bags which are clearly labelled.
- All dust containing lead or other contaminants is to be disposed of as far as reasonably practicable in a manner, and at a site, approved by Safe Work NSW, NSW Office of Environment and Heritage [OEH], appropriate disposal Authority or WOOLLAHRA MUNICIPAL Council.

4. AREAS NOT ASSESSED

All areas associated with the proposed Contract works were able to be assessed with the exception of the under-floor space.

5. UNDETECTED HAZARDOUS MATERIALS

Due to the level of accessibility including the presence of obstructions the overall degree of risk of **undetected** hazardous materials is considered as far as *reasonably practicable* to be:

Low	Moderate	✓	Moderate to High		High	
-----	----------	---	------------------	--	------	--

CONFIRMATION

This document confirms that the existing residence layout described in this report has been assessed as far as *reasonably practicable* for the inclusion of hazardous materials i.e. materials "that may" contain asbestos [ACM] or [ACD], paints "that may" contain lead or synthetic mineral fibres [SMF] in the existing structure.

This assessment and report was carried out by: Mark Spindler

Signed for and on behalf of JONSPIN Building Services Pty. Limited

Mark Spindler Date of Issue: 13th January 2017