## ASBESTOS REGISTER



SITE: 7820 Munro.Maguire 55 Churchill Drive, Winston Hills LAST UPDATED: 24/04/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Туре	Friable / Non-Friable	Quantity	Condition	Assessment / Action
21/03/2017	Eave soffit lining	Asbestos cement sheet	Non-friable	24.5 sqm	Good/stable Painted	Protect the ACM from damage during the course of the works
21/03/2017	Front porch soffit lining	Asbestos cement sheet	Non-friable	1.5 sqm	Good/stable Painted	Protect the ACM from damage during the course of the works
21/03/2017	Bathroom wall lining	Asbestos cement sheet	Non-friable	9.5 sqm	Good/stable Painted	Protect the ACM from damage during the course of the works
21/03/2017	Laundry wall lining	Asbestos cement sheet	Non-friable	12 sqm	Good/stable Painted	Protect the ACM from damage during the course of the works
21/03/2017	WC wall lining	Asbestos cement sheet	Non-friable	4 sqm	Good/stable Painted	Protect the ACM from damage during the course of the works
21/03/2017	Electrical meter board	ACM	Non-friable	0.25 sqm	Good/stable	Protect the ACM from damage during the course of the works

Issued: February 2017

Version: 1.0

Page 1 of 1
Approved by: WHS & Human Resources Coordinator
Printed: 24/04/2017 2:01 PM