Fresh Start

Safe Work Method Statement

Project / Location: All Jobs

version 1.0

Activity / Task: Scaffold - Erection

Company: Fresh Start

Signed by: Chris Moerman Date: 09/11/2015

• Exposure to noise.

Principle Contractor: Cape Cod

Accepted by: Jo Moerman Date: 28/08/2016

Steps	Potential Hazards	Controls / Responsible Person(s)
1. Access to site.	 Slips, trips, falls and accessibility. UV / weather exposure. 	 Site specific induction. By: Fresh Start All "workers" to read the General Construction Safety Plan signage and Risk Assessment form before entering site. By: Fresh Start Tool box talk to highlight any WHS concerns relative to the site. By: Fresh Start Ensure that the site and work place access is unobstructed. By: Principle Contractor & Fresh Start Ensure all weather access to work areas. By: Principle Contractor Wear appropriated PPE - hat, long sleeves, sun screen, sunglasses, and fluids and reduce exposure where possible. By: Fresh Start Storage of materials /plant in designated areas. By: Fresh Start Provide and maintain barricades to all materials stored on footpath and on site. By: Fresh Start Regular site clean ups. By: Principle Contractor
2. Unloading tools, ladders and scaffold components	 Manual handling injuries. Slips, trips and falls. Proximity of other "workers". Public access. 	 Team lifting and carrying. By: Fresh Start Training of "workers" in correct lifting and carrying methods. By: Fresh Start Unload and move the tools, ladders and scaffold components to a designated area to keep footpath / work place access clear. By: Fresh Start
3. Setting up	 Manual handling injuries. Slips, trips and falls. Falls from height. Uneven site. UV / weather exposure. Proximity of other "workers". Public access. 	 Assess the site conditions including the weather and conduct a Risk Assessment before commencing. By: Fresh Start Set up in a clear area and maintain a clear travel path. By: Fresh Start Identify the location of the electrical, sewer and stormwater services. By: Fresh Start Identify that the electrical service has been isolated or safely recommissioned before commencing work. By: Principle Contractor All scaffolding is to be erected by WorkCover NSW certified Scaffolders. By: Fresh Start Training of "workers" in the setting up of ladders, electrical equipment and use of safety harnesses. By: Fresh Start Ensure the proper use of all safety guards and systems provided. By: Principle Contractor & Fresh Start Ensure that all power tools and electrical leads have current tagging. By: Fresh Start Ensure that power tools are attached to a residual current device [RCD]. By: Fresh Start Provide "Restricted Access" warning signage. By: Fresh Start Establish a "No access area" to work areas by barricading to prevent access to the area of work. Provide a spotter where necessary. By: Fresh Start
4. Erection of scaffold to 2.0m. Passing scaffolding components from building level or ground.	 Slips, trips, falls and accessibility. Fall from heights. Manual handling injuries. Sprains and strains. Cuts and abrasions. Electrocution. 	 Assess the site conditions and conduct a Risk Assessment before commencing. By: Fresh Start Identify the location of the electrical, sewer and stormwater services. By: Fresh Start Identify that the electrical service has been isolated and that 'tiger tails' are in place as protection from overhead wires and points of attachment before commencing. By: Principle Contractor & Fresh Start Provide "Restricted Access" warning signage. By: Fresh Start Establish a "No access area" below overhead work areas by barricading to prevent access to the area of work. Provide a spotter where necessary. By: Fresh Start

• Training of "workers" in correct lifting and carrying methods. By: Fresh Start

- Exposure to dust.
- UV / weather exposure.
- Proximity of other "workers".
- Public access.
- Ensure correct lifting and carrying techniques are used at all times. By: Fresh Start
- Rotate "workers" and vary tasks performed. By: Fresh Start
- Ensure "workers" have safety glasses, noise and dust protection, appropriate protective footwear, hard hat and gloves. By: Fresh Start
- Training of "workers" in the safe use of power tools and equipment. By: Fresh Start
- Ensure that all power tools have working safety guards. By: Fresh Start
- Storage of surplus scaffold components in designated areas so not to endanger the public or other "workers". By: Fresh Start
- Maintain a clean and tidy work area. By: Fresh Start
- Clearly display "Scaffold incomplete" sign to incomplete scaffold at all times prior to sign off of the scaffold. By: Fresh Start

- Work from two [2] plank width working platform
- Manual handling injuries.
- Sprains and strains.
- Cuts and abrasions.
- Flectrocution
- Exposure to noise.
- Exposure to dust.
- UV / weather exposure.
- Proximity of other "workers".
- Public access.

- Identify that the electrical service has been isolated and that 'tiger tails' are in place as protection from overhead wires and points of attachment before commencing. By: Fresh Start
 - Provide "Restricted Access" warning signage. By: Fresh Start
 - Establish a "No access area" below overhead work areas by barricading to prevent access to the area of work. Provide a spotter where necessary. By: Fresh Start
 - Training of "workers" in correct lifting and carrying methods. By: Fresh Start
 - Ensure correct lifting and carrying techniques are used at all times. By: Fresh Start
 - Rotate "workers" and vary tasks performed. By: Fresh Start
 - Training of "workers" in the setting up of ladders and use of safety harnesses. By: Fresh Start
 - Ensure workers have safety glasses, noise and dust protection, appropriate protective footwear, hard hat and gloves. By: Fresh Start
 - Training of "workers" in the safe use of power tools and equipment. By: Fresh Start
 - Ensure that all power tools have working safety guards. By: Fresh Start
 - Storage of surplus scaffold components in designated areas so not to endanger the public or other "workers" By: Fresh Start
 - Maintain a clean and tidy work area. By: Fresh Start
 - Clearly display "Scaffold incomplete" sign to incomplete scaffold at all times prior to sign off of the scaffold. By: Fresh Start

- 6. Continue to erect scaffold top out. Access to be built up with scaffold. Access to scaffold by ladder. balcony deck internal stair or ladder.
- accessibility.
- Fall from heights
- Manual handling injuries.
- Sprains and strains.
- Cuts and abrasions.
- Electrocution.
- Exposure to noise.
- Exposure to dust
- UV / weather exposure.
- Proximity of other "workers".
- Public access.

- Slips, trips, falls and Assess the site conditions and conduct a Risk Assessment before commencing. By: Fresh Start
 - Identify that the electrical service has been isolated and that 'tiger tails' are in place as protection from overhead wires and points of attachment before commencing. By: Principle Contractor &
 - Provide "Restricted Access" warning signage. By: Principle Contractor
 - Establish a "No access area" below overhead work areas by barricading to prevent access to the area of work. Provide a spotter where necessary. By: Fresh Start
 - Training of "workers" in correct lifting and carrying methods. By: Fresh Start
 - Ensure correct lifting and carrying techniques are used at all times. By: Fresh Start
 - Rotate "workers" and vary tasks performed. By: Fresh Start
 - Ensure "workers" have safety glasses, noise and dust protection, appropriate protective footwear, hard hat and gloves. By: Fresh Start
 - Training of "workers" in the safe use of power tools and equipment. By: Fresh Start
 - Ensure that all power tools have working safety guards. By: Fresh Start
 - Storage of surplus scaffold components in designated areas so not to endanger the public or "workers". By: Fresh Start
 - Maintain a clean and tidy work area. By: Fresh Start
 - Clearly display "Scaffold incomplete" sign to incomplete scaffold at all times prior to sign off of the scaffold. By: Fresh Start

Person responsible for ensuring compliance with SWMS: Person responsible for reviewing SWMS control measures: