ASBESTOS REGISTER



SITE: 7838 Thomson.Dekany 52 Tenterden Road, Botany LAST UPDATED: 30/10/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Туре	Friable / Non-Friable	Quantity	Condition	Assessment / Action
26/10/2017	Verandah soffit lining (front section)	Asbestos cement sheet	Non-friable	14.5 sqm	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
26/10/2017	Bathroom wall and ceiling lining	Asbestos cement sheet	Non-friable	3.5 sqm (ceiling) 19.5 sqm (walls)	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
26/10/2017	Laundry wall and ceiling lining	Asbestos cement sheet	Non-friable	2.5 sqm (ceiling) 12 sqm (walls)	Good/Stable Surface coated to the exposed areas	Protect the retained ACM from damage during the course of the works
26/10/2017	Electrical meter board lower lining	Asbestos cement sheet	Non-friable	0.5 sqm	Good/Stable	Protect the retained ACM from damage during the course of the works

Issued: February 2017

Version: 1.0

Page 1 of 1
Approved by: WHS & Human Resources Coordinator
Printed: 30/10/2017 9:11 AM