

## **SAFE WORK METHOD STATEMENT**

Page 1 of 6

Company [PCBU]:	Solid Foundations	Project Name/No:	All Jobs
Work Activity / Task:	SCAFFOLDER - DISMANTLE	Principal Contractor:	Cape Cod Australia Pty Ltd
Prepared by:	Liam McDonagh	Date: 19/9/2014	
Signature:	LM Dona	Note: Sign off to be provided at Tool Box talk	

Note: Review of Control Measures -

If there are any tasks that may be included by way of variation to the plans or an alternative approach to the set task. It is a requirement to carry out a specific Risk Assessment for the tasks.

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
1	Access to site.	<ul> <li>Slips, trips, falls and accessibility.</li> <li>UV / weather exposure.</li> </ul>	<ul> <li>Site specific induction.</li> <li>All "workers" to read the General Construction Safety Plan signage and Risk Assessment form before entering site.</li> </ul>	BULLISIZ
			Tool box talk to highlight any WHS concerns relative to the site.	^ 1
			Ensure that the site and work place access is unobstructed.	11
			<ul> <li>Ensure all weather access to work areas.</li> </ul>	((
			<ul> <li>Wear appropriated PPE - hat, long sleeves, sun screen, sunglasses and fluids and reduce exposure where possible.</li> </ul>	11
			<ul> <li>Storage of materials /plant in designated areas.</li> </ul>	((
			<ul> <li>Provide and maintain barricades to all materials stored on footpath and on site.</li> </ul>	"
			Regular site clean ups.	DU 152-
2	Unloading tools and equipment	<ul> <li>Manual handling injuries.</li> <li>Slips, trips and falls.</li> </ul>	<ul> <li>Team lifting and carrying.</li> <li>Training of "workers" in correct lifting and carrying methods.</li> </ul>	Compaced
		<ul> <li>Proximity of other "workers".</li> </ul>	<ul> <li>Unload and move the tools and equipment to a designated area to keep footpath / work place</li> </ul>	1

Rev	iewed	l by:
-----	-------	-------

Gary Klomp

Principal Contractor's Representative

Construction Manager

Position

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
_		Public access.	access clear.	
3	Dismantling	<ul> <li>Slips, trips, falls and accessibility.</li> <li>Fall from heights.</li> <li>Falling objects.</li> </ul>	<ul> <li>Assess the site conditions including the weather and conduct a Risk Assessment before commencing.</li> <li>Set up in a clear area and</li> </ul>	BULLER
		<ul><li>Manual handling injuries.</li><li>Sprains and strains.</li></ul>	<ul><li>maintain a clear travel path.</li><li>Identify the location of the</li></ul>	BUILDER
		<ul> <li>Cuts and abrasions.</li> <li>Electrocution.</li> </ul>	electrical service.      Identify that electrical service     has been isolated and that 'times'	.301(33)-
		<ul><li>Exposure to noise.</li><li>Exposure to dust</li></ul>	has been isolated and that 'tiger tails' are in place as protection from overhead wires and points	// // // // // // // // // // // // //
		UV / weather exposure.	of attachment before commencing.	
		• Proximity of other "workers".	. Dv workcover ivsw certilled	Compacto
	Public access.	<ul> <li>Public access.</li> <li>Ensure "workers" have safety glasses, noise and dust protection, appropriate protective footwear, hard hat and gloves.</li> </ul>	1(	
			Training of "workers" in the setting up of ladders, electrical equipment and use of fall arrest systems [harnesses].	11
			Ensure the proper use by     "workers" of all safety guards     and fall arrest systems provided.	//
		Ensure Scaffolder ["worker"] is harnessed up to scaffold at all times when dismantling components.	11	
		•	Ensure that all power tools and electrical leads have current tagging.	//
			Ensure that power tools are attached to a residual current device [RCD].	"(
			Provide "Restricted Access"	BULL DO

Reviewed by:	Gary Klomp	Construction Manager
·	Principal Contractor's Representative	Position
		. 6 ~ . <b>\</b>

17/12/2014 Date

ltem	Job Step	Potential Hazard	Controls	Responsible Person/s
			<ul> <li>warning signage.</li> <li>Establish a "No access area" to work areas by barricading to prevent access to the area of work. Provide a spotter where necessary.</li> <li>Ensure working platforms [decks] are clean.</li> <li>Dismantle shade cloth and mesh by undoing from bottom to top.</li> </ul>	CONTLACTO
			Pull shade cloth and mesh into scaffold and pass down to man ["worker"] on ground.	"
			Ensure that the dismantling of scaffold components is only undertaken once shade cloth and mesh has been removed to reduce wind loading on the scaffold.	(
			Clearly display "Scaffold incomplete" sign to incomplete scaffold if scaffold is left unattended.	1
4	Dismantling Kickboards Handrails Dismantle deck or wait until access to lift below	<ul> <li>Slips, trips, falls and accessibility.</li> <li>Fall from heights.</li> <li>Falling objects.</li> <li>Manual handling injuries.</li> <li>Sprains and strains.</li> </ul>	<ul> <li>Assess the site conditions including the weather and conduct a Risk Assessment before commencing.</li> <li>Set up in a clear area and maintain a clear travel path.</li> <li>Identify the location of the electrical services.</li> </ul>	BULDEL CONTRACTO BULDE
		<ul> <li>Cuts and abrasions.</li> <li>Electrocution.</li> <li>Exposure to noise.</li> <li>Exposure to dust.</li> </ul>	Identify that the electrical service has been isolated or safely recommissioned before commencing work.	u u
		<ul> <li>UV / weather exposure.</li> <li>Proximity of other "workers".</li> <li>Public access.</li> </ul>	Identify that the electrical service has been isolated and that 'tiger tails' are in place as protection from overhead wires and points of attachment before commencing.	()

Reviewed by:	Gary Klomp
-	Principal Contractor's Representative
	Signature

Construction Manager
Position

17/12/2014 Date

Item	Job Step	Potential Hazard		Controls	Responsible Person/s
			•	All scaffolding is to be dismantled by WorkCover NSW certified Scaffolders.	CONTRACT
			•	Ensure "workers" have safety glasses, noise and dust protection, appropriate protective footwear, hard hat and gloves.	"
			•	Training of "workers" in the setting up of ladders, electrical equipment and use of fall arrest systems [harnesses].	2 F 11 ;
			•	Ensure the proper use by "workers" of all safety guards and fall arrest systems provided.	· 11
			•	Ensure Scaffolder ["worker"] is harnessed up to scaffold at all times when dismantling components	"
			•	Ensure Scaffolder ["worker"] only disconnects when working on two [2] planks and protected by handrail.	٧)
			•	Ensure that all power tools and electrical leads have current tagging.	ĺ\
			•	Ensure that power tools are attached to a residual current device [RCD].	11
			•	Provide "Restricted Access" warning signage.	, ROLLDE
			•	Establish a "No access area" to work areas by barricading to prevent access to the area of work. Provide a spotter where necessary.	BULLSER
			•	Ensure working platforms [decks] are clean.	11
			•	Dismantle shade cloth and mesh by undoing from bottom to top	"
			•	Pull shade cloth and mesh into	<u> </u>

Reviewed by:	Gary Klomp	Construction Manage
•	Principal Contractor's Representative	Position
		· · · · · · · · ·

17/7/2014 nature Date

ltem	Job Step	Potential Hazard	Controls	Responsible Person/s
			scaffold and pass down to man on ground.	11
			<ul> <li>Ensure scaffold ties are only removed when shade cloth and mesh has been dismantled and only once stripping has reached the level of the tie.</li> </ul>	CONTRACTO
:			<ul> <li>Clearly display "Scaffold incomplete" sign to incomplete scaffold if scaffold is left unattended.</li> </ul>	"
5	Continue to dismantle scaffold.	<ul> <li>Slips, trips, falls and accessibility.</li> <li>Fall from heights.</li> <li>Falling objects.</li> </ul>	<ul> <li>Assess the site conditions including the weather and conduct a Risk Assessment before commencing.</li> </ul>	BULLIST OF COURSE
	Scaffolder to work back	Manual handling	Set up in a clear area and maintain a clear travel path.	CONTACTOR
	towards scaffold access.	<ul><li>injuries.</li><li>Sprains and strains.</li></ul>	<ul> <li>Identify the location of the electrical service.</li> </ul>	Birash
	Once access is disconnected then dismantle next lift.	<ul> <li>Cuts and abrasions.</li> <li>Electrocution.</li> <li>Exposure to noise.</li> <li>Exposure to dust</li> <li>UV / weather</li> </ul>	<ul> <li>Identify that electrical services have been isolated and that 'tiger tails' are in place as protection from overhead wires and points of attachment before commencing.</li> </ul>	U\\
		<ul><li>exposure.</li><li>Proximity of other "workers".</li></ul>	All scaffolding is to be dismantled by WorkCover NSW certified Scaffolders.	CONTRACTO
	Public access.	<ul> <li>Ensure "workers" have safety glasses, noise and dust protection, appropriate protective footwear, hard hat and gloves.</li> </ul>	))	
			<ul> <li>Training of "workers" in the setting up of ladders, electrical equipment and use of fall arrest systems [harnesses].</li> </ul>	"
			<ul> <li>Ensure the proper use of all safety guards and fall arrest systems provided.</li> </ul>	11
			Ensure that all power tools and	

Reviewed by:	Gary Klomp	Construction Manager
•	Principal Contractor's Representative	Position
		17 12 2014
	Signature	Date

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
			electrical leads have current tagging.	11
			Ensure Scaffolder ["worker"] is harnessed up to scaffold at all times when dismantling components	Π
			<ul> <li>Ensure Scaffolder ["worker"] only disconnects when working on two [2] planks and protected by handrail.</li> </ul>	K
			Ensure that power tools are attached to a residual current device [RCD].	Burse
			<ul> <li>Provide "Restricted Access" warning signage.</li> </ul>	Burses
!			Establish a "No access area" to work areas by barricading to prevent access to the area of work. Provide a spotter where necessary.	- 1/
			Ensure working platforms [decks] are clean.	CONTRACT
			Ensure scaffold ties are only removed when shade cloth and mesh has been dismantled and only once stripping has reached the level of the tie.	11
			Clearly display "Scaffold incomplete" sign to incomplete scaffold if scaffold is left unattended.	/(

Reviewed by:	Gary Klomp
	Principal Contractor's Representative
	Signature
	Signature

Construction Manager
Position

17/13/2014 Date