SAFE WORK METHOD STATEMENT

Page 1 of 7 v1.13

| Company Name: | Fresh Start Constructions | Project Name/No: | All Jobs |
|-----------------------|---------------------------|--|------------------------------|
| Work Activity / Task: | DEMOLITION - MANUAL | Principal Contractor: | Cape Cod Australia Pty. Ltd. |
| Prepared by: | Christian Moerman | Date: 17/9/14 | |
| Signature: | comune | Note: Sign off to be provided at Tool Box talk | |

Note: Review of Control Measures - If there are any tasks that may be included by way of variation to the plans or an alternative approach to the set task, it is a requirement to carry out a "Specific Risk Assessment" for the tasks.

| Item | Job Step | Potential Hazard | Controls | Responsible Person/s |
|------|--|--|--|---|
| 1 | Access to site | Slips, trips, falls and accessibility. UV light / weather exposure. | long sleeves, sun screen, sunglasses and fluids and reduce exposure where possible. Provision of designated waste areas. Storage of materials in designated areas. Regular site clean ups. | The Bulder Fresh STAT Fresh STAT Fresh STAT Fresh STAT Fresh STAT The Bulder Fresh STAT The Bulder Fresh STAT Fresh STAT Fresh STAT Fresh STAT Fresh STAT |
| 2 | Unloading plant, equipment and tools | Manual task injuries Slips, trips and falls. Proximity of other "workers". Public access. | Team lifting and carrying. Training of "workers" in correct lifting and carrying methods. Unload and move the equipment to designated area to keep footpath / work place access clear. | Fresh Start Fresh Start |
| 3 | Setting up | Manual task injuries | Set up in a clear area and | |

| Reviewed by: | Gary Klomp | Construction Manager | |
|--------------|-----------------------|----------------------|--|
| • | On behalf of Cape Cod | Position | |
| | | | |
| | | 19/0/10 | |

Date

Signature

Page 2 of 7 v1.13

| Item | Job Step | Potential Hazard | Controls | Responsible Person/s |
|------|--------------------------------|---|--|---|
| | equipment | Slips, trips and falls. Proximity of other "workers". Public access. | maintain a clear travel path. Training of "workers" in setting up of electrical leads and power tools and pneumatic tools. Ensure proper use of all safety | Fresh 572-7 Fresh 572-7 Fresh 572-7 |
| | | | guards provided. • Ensure that all power tools and electrical leads have current tagging. | |
| | | | Ensure that all power tools are attached to a residual current device [RCD]. | F-051 57e-7 |
| 4 | Stripping of external cladding | Slips, trips, falls and accessibility UV light / weather | Assess the site conditions and conduct a Site Specific Risk Assessment before commencing. | Fresh 574-7 |
| | | exposure Electrocution Hazardous materials Exposure to dust Exposure to noise | Identify that the electrical service has been isolated and that 'tiger tails' are in place as protection from overhead wires and points of attachment before commencing installation work. | Fresh Start |
| | | Manual task injuriesCuts and abrasions.Proximity of other | Provide "Demolition in Progress" and "Restricted Access" warning signage. | The bulla |
| | | "workers". • Public access. | Establish a "No access area" to work areas by barricading to prevent access to the area of work. Provide a 'spotter' where necessary. | Fresh Start |
| | | | Identify any products or materials that <i>may</i> contain asbestos [ACM]. | The Builder Fresh 57427 Fresh 57427 |
| : | | | Ensure that the scaffolding is safe and erected by a qualified Scaffolder before commencing. | |
| : | i | | Ensure that the scaffolding and edge protection is in place before commencing. | Fresh 570-7 |
| | | | Correct use of ladder. Use appropriate PPE - safety | E-056 5700-7 |
| | | | Scaffolder before commencing. | Fresh 570 Fresh 570 Fresh 570 |

| Reviewed by: | Gary Klomp | Construction Manager | |
|--------------|-----------------------|----------------------|--|
| | On behalf of Cape Cod | Position | |

Date

Signature

Page **3** of **7** v1.13

| Item | Job Step | Potential Hazard | Controls | Responsible Person/s |
|------|-------------------------------------|---|--|---|
| 5 | Demolishing of ground floor by hand | Slips, trips, falls and accessibility. UV light / weather exposure. Hazardous materials. Identification of services. Electrocution. Gas explosions. Falling objects. Exposure to dust. Exposure to noise. Manual task injuries Heavy lifting. Cuts and abrasions. Proximity of other "workers". Public access. | protection, dust protection [disposable], gloves and hard hats. Training of "workers" in the safe use of hand tools and power tools. Systematic safe removal of materials. Team lifting and carrying. Storage of materials in designated waste areas Regular site clean ups. Ensure materials are not stored on roof surface or scaffold. Assess the site conditions and conduct a Site Specific Risk Assessment before commencing. Identify any products or materials that may contain asbestos [ACM]. Identify services and make sure all electrical, gas, water and sewerage services have been isolated or safely relocated before commencing. Use Licensed Electrician and Plumber to isolate, disconnect and relocate existing services. Provide "Demolition in Progress" and "Restricted Access" warning signage. Establish a "No access area" to work areas by barricading to prevent access to the area of work. Provide a spotter where necessary. Monitor air quality. Ensure that all exposed openings and voids in the floor are guard railed or covered. | Fresh Start Fresh Start Fresh Start Fresh Start The builder Fresh Start The builder The Start |

| Reviewed by: | Gary Klomp | Construction Manager |
|--------------|-----------------------|----------------------|
| | On behalf of Cape Cod | Position |
| | | |

Date

Signature

Page 4 of 7 v1.13

| Item | Job Step | Potential Hazard | Controls | Responsible Person/s |
|------|-------------------------------------|--|--|--------------------------|
| | | | Use appropriate PPE – safety glasses, footwear, noise / hearing protection, dust protection [disposable], gloves, and hard hats. | F-054 574-7 |
| | | | Training of "workers" in the safe use of pneumatic and electrical power tools. | F-054 574-7 |
| | | | Systematic safe removal of materials. | Fresh 5727 Fresh 5727 |
| | | | Team lifting and carrying. Provide shade cloth around work area and wet down dust as | The bulder |
| | | | required to prevent wind borne dust. | 1 574-7 |
| | | | Storage of materials in designated waste areas Regular site clean ups. | Fest STAT The bulla |
| | | | Ensure all exposed nails are removed. | Fress Stary |
| 6 | Demolishing brickwork by hand | Slips, trips, falls and accessibility. Hazardous materials. | Assess the site conditions and conduct a Risk Assessment before commencing. | Frest Stury |
| | | Identification of services. | Provide "Demolition in Progress" and "Restricted Access" warning | The builder |
| : | | Electrocution. Gas explosions. Falling objects. Exposure to dust. Exposure to noise. | signage. • Establish a "No access area" to work areas by barricading to prevent access to the area of work. Provide a spotter where necessary. | Fresh Sturt |
| | | Manual task injuries Heavy lifting. | Identify any products or materials that <i>may</i> contain asbestos [ACM]. | Frest 572-7 |
| | | Cuts and abrasions. Proximity of other trades. | Identify services and ensure all electrical, gas, water and sewerage services have been isolated or safely relocated before commencing. | |
| | | | Use Licensed Electrician and Plumber to isolate, disconnect | The builder |

| Reviewed by: | Gary Klomp | Construction Manager |
|--------------|-----------------------|----------------------|
| · | On behalf of Cape Cod | Position |

Date

Signature

Page **5** of **7** v1.13

| Item | Job Step | Potential Hazard | Controls | Responsible Person/s |
|------|--------------------------------------|---|---|--|
| | | | and relate existing services. Use appropriate PPE - safety glasses, footwear, noise / hearing protection, dust protection [disposable], gloves, and hard | F-854 574-7 |
| | | | hats. Training of "workers" in safe use of pneumatic and electrical power tools. | F-65 574-7 |
| | : | | Systematic safe removal of materials. | Fresh 570-7 |
| | | | Team lifting and carrying. To upper floor areas provide a shute for materials into | Fross Grant Fresh Start The buller |
| | | : | designated waste area as required. Provide a spotter where necessary. | Fresh 579-7 |
| | | | Monitor air quality. Provide shade cloth around work area and wet down dust as required to prevent wind borne dust. | The Builder |
| | | : | Storage of materials in designated waste areas Regular site clean ups. | Fresh STAT The builder Fresh STAT |
| 7 | Stripping of existing roof frame and | Slips, trips, falls and accessibility.UV light / weather | Assess the site conditions including the weather and conduct a Site Specific Risk | |
| | covering | exposure. Fall from height. Hazardous materials. Identification of | Assessment before commencing. Identify any products or materials that may contain asbestos. | The built- Fress 5727 Fress 5727 |
| | | services. • Electrocution. • Gas explosions. | Identify services and ensure all electrical, gas, water and sewerage services have been isolated or safely relocated | Fros 57a-7 |
| | | Falling objects.Exposure to dust.Exposure to noise. | before commencing. Use Licensed Electrician and Plumber to isolate, disconnect | The bullar |
| | | Manual task injuriesHeavy lifting. | and relate existing services. • Training of "workers" in safe | F-151 574-7 |

| Reviewed by: | Gary Klomp | |
|--------------|-----------------------|--|
| - | On hehalf of Cane Cod | |

Construction Manager Position

Signature Date

Page 6 of 7 v1.13

| Item | Job Step | Potential Hazard | Controls | Responsible Person/s |
|------|----------|--|---|---|
| | | Cuts and abrasions. Proximity of other trades | working at heights. • Provide "Demolition in Progress" and "Restricted Access" warning | The builder |
| | | ti ddes | signage. • Establish a "No access area" below overhead work areas by barricading to prevent access to the area of work. Provide a 'spotter' where necessary. | Frest 579-7 |
| | | | Ensure that the scaffolding and edge protection is in place before commencing. | Fresh 571-7 Fresh 571-7 |
| | | | Correct use of ladder | |
| | | | Use appropriate PPE - safety glasses, footwear, noise / hearing protection, dust protection [disposable], gloves and hard hats. | |
| | | | Training of "workers" in the safe use of hand tools and power tools. | Fresh Start |
| | | | Systematic safe removal of materials. | Frest STR-7 Frest STR-7 Frest STR-7 The builder |
| | | | Team lifting and carrying. | F-05 572-1 |
| | | 1 1 | Provide a shute for materials into | Fress + 578-7 |
| | | | designated waste area as required. Provide a spotter where necessary. | |
| | | | Provide shade cloth / mesh around work area and wet down dust as required to prevent wind borne dust. | The builter |
| | | | Storage of materials in | Frest 57-7 |
| | | | designated waste areas Regular site clean ups. | The bulder |
| | | | Ensure all roof tarps are tied down and not weighted with tiles. | Fresh STAT The builder Fresh STAT |
| | | | Ensure materials are not stored on the roof or scaffold. | Fresh Start |

| Reviewed by: | Gary Klomp | Construction Manager |
|--------------|-----------------------|----------------------|
| • | On behalf of Cape Cod | Position |
| | | |

Date

Signature

Page **7** of **7** v1.13

| Item | Job Step | Potential Hazard | Controls | Responsible Person/s |
|------|-------------------------------------|---|--|---|
| 8 | Site clean up on completion of work | Manual task injuries Exposure to dust Exposure to hazardous substances- | Remove any temporary barricades if no longer required Place all rubbish / debris in designated waste storage area Leave site / work area in a clean and tidy condition | Fresh 579-7 Fresh 579-7 Fresh 579-7 |

| Reviewed by: | Gary Klomp | Construction Manager | |
|--------------|-----------------------|----------------------|--|
| • | On behalf of Cape Cod | Position | |
| | | | |

Signature Date