ASBESTOS REGISTER



SITE: 7840 Biro 3 Nabiac Place, Westleigh LAST UPDATED: 25/10/2017

JOB NUMBER CLIENT ADDRESS

| Date Identified | Location of ACM | Туре | Friable / Non-Friable | Quantity | Condition | Assessment / Action |
|--------------------|----------------------|-----------------------|--------------------------|----------|---|---|
| 23/10/2017 | Eave soffit lining | Asbestos cement sheet | Non-friable | 30 sqm | Good/Stable Surface coated to the exposed areas | Protect the retained ACM from damage during the course of the works |
| 23/10/2017 | Gable end cladding | Asbestos cement sheet | Non-friable | 6 sqm | Good/Stable Surface coated to the exposed areas | Protect the retained ACM from damage during the course of the works |
| 23/10/2017 | Porch soffit lining | Asbestos cement sheet | Non-friable | 13.5 sqm | Good/Stable Surface coated to the exposed areas | Protect the retained ACM from damage during the course of the works |
| 23/10/2017 | Laundry wall lining | Asbestos cement sheet | Non-friable | 15 sqm | Good/Stable Surface coated to the exposed areas | Protect the retained ACM from damage during the course of the works |
| 23/10/2017 | Bathroom wall lining | Asbestos cement sheet | Non-friable | 15 sqm | Good/Stable Surface coated to the exposed areas | Protect the retained ACM from damage during the course of the works |

ASBESTOS REGISTER



| 23/10/2017 | Ensuite wall lining | Asbestos cement sheet | Non-friable | 15 sqm | Good/Stable Surface coated to the exposed areas | Protect the retained ACM from damage during the course of the works |
|------------|---------------------------|-----------------------|-------------|---------|---|---|
| 23/10/2017 | Kitchen floor covering | Asbestos cement sheet | Non-friable | 7.5 sqm | Good/Stable Surface coated to the exposed areas | Protect the retained ACM from damage during the course of the works |
| 23/10/2017 | Garage ceiling lining | Asbestos cement sheet | Non-friable | 24 sqm | Good/Stable Surface coated to the exposed areas | Protect the retained ACM from damage during the course of the works |
| 23/10/2017 | Electrical meter board | ACM | Non-friable | 0.5 sqm | Good/Stable | Protect the retained ACM from damage during the course of the works |

Issued: February 2017

Version: 1.0

Page 2 of 2 Approved by: WHS & Human Resources Coordinator Printed: 25/10/2017 8:29 AM