Company [PCBU]:	San Sing Enterprises	Project Name/No:	All Jobs		
Work Activity / Task:	Demolition and removal of materials by hand	Principal Contractor:	Cape Cod Australia Pty Ltd		
Prepared by:	Brian San Sing	Date:	8/9/14		
Signature:	2 may	Note: Sign off to be provided at Tool Box talk			

Note: Review of Control Measu	res	
-------------------------------	-----	--

If there are any tasks that may be included by way of variation to the plans or an alternative approach to the set task. It is a requirement to carry out a specific Risk Assessment for the tasks.

Task/Problem	Hazard	Lik	kelih	00	R	esu	llt	-	Possible Control	Action By	Date
Variation to plan	Unknown		d					Priority	Tool Box Talk	Contractor	
Change of Brief		Likely	Possible	Unlikely	Major	Severe	Minor	Pric	Work Method Statement	Supervisor	
		٧			٧			1			

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
1	Access to site	 Slips, trips, falls and accessibility. UV / weather exposure. 	 Site specific induction. All "workers" to read the General Construction Safety Plan signage and Risk Assessment form before entering site. 	Cope (Od 55E
			Tool box talk to highlight any WHS concerns relative to the site.	SSE
			 Ensure that site and work place access is unobstructed. 	Cope los
			Ensure all weather access to work areas.	cope led

eviewed by:	Gary Klomp	<u>Construction Manager</u>
	Principal Contractor's Representative	Position
		10 10 Cm A
	Signature	Date

ltem	Job Step	Potential Hazard	Controls	Responsible Person/s
			 Wear appropriated PPE - hat, long sleeves, sun screen, sunglasses and fluids and reduce exposure where possible. Provision of designated waste areas. Storage of materials in designated areas. Regular site clean ups. 	SSE Cope cod SSE Cope cod
2	Unloading plant, equipment and tools	 Manual handling injuries Slips, trips and falls. Proximity of other "workers". Public access. 	 Team lifting and carrying. Training of "workers" in correct lifting and carrying methods. Unload and move the equipment to designated area to keep footpath / work place access clear. 	556 556 556
3	Setting up equipment	 Manual handling injuries Slips, trips and falls. Proximity of other "workers". 	 Set up in a clear area and maintain a clear travel path. Training of "workers" in setting up of electrical leads and power tools and pneumatic tools. 	55E 55E
		Public access.	 Ensure proper use of all safety guards provided. Ensure that all power tools and electrical leads have current tagging. 	55 E 55E
			Ensure that all power tools are attached to a residual current device [RCD].	Sjé
the state of the s	Stripping of external cladding	 Slips, trips, falls and accessibility UV / weather exposure Electrocution Hazardous materials 	 Assess the site conditions and conduct a Risk Assessment before commencing. Identify that the electrical service has been isolated and that 'tiger tails' are in place as protection from overhead wires and points 	Cape Cod

Reviewed by:	Gary Klomp
	Principal Contractor's Representative
	Signature

Construction Manager
Position

10 19 20Kf

item	Job Step	Potential Hazard	Controls	Responsible Person/s
		 Exposure to dust Exposure to noise Manual handling Cuts and abrasions. Proximity of other "workers". Public access. 	of attachment before commencing installation work. Provide "Demolition in Progress" and "Restricted Access" warning signage. Establish a "No access area" to work areas by barricading to prevent access to the area of work. Provide a spotter where necessary. Identify any products or materials that may contain	Cyc Cod
			 asbestos. Ensure that the scaffolding is safe and erected by a qualified Scaffolder before commencing. Ensure that the scaffolding and edge protection is in place before commencing. 	lige lod
			 Correct use of ladder. Use appropriate PPE – safety glasses, footwear, noise / hearing protection, dust protection [disposable], gloves and hard hats. 	55E 55E
, , , , , , , , , , , , , , , , , , , ,			Training of "workers" in the safe use of hand tools and power tools. System said of "	SSE
			 Systematic safe removal of materials. Team lifting and carrying. 	55E 55E
_			Storage of materials in designated waste areas	SSE Cyc lad Cyc lad Cyc lad
	molishing of und floor by	Slips, trips, falls and accessibility.	Assess the site conditions and conduct a Risk Assessment	7

Reviewed by:	Gary Klomp Principal Contractor's Representative	Construction Manager
	a representative	Position
	Signature	10 10 201f

Item Job Step	Potential Hazard	Controls	Responsible Person/s
hand	 UV / weather exposure. Hazardous materials. Identification of services. Electrocution. Gas explosions. Falling objects. Exposure to dust. Exposure to noise. Manual handling. Heavy lifting. Cuts and abrasions. Proximity of other "workers". Public access. 	 Use appropriate PPE – safety glasses, footwear, noise / hearing protection, dust protection [disposable], gloves, and hard hats. Training of "workers" in the safe use of pneumatic and electrical power tools. Systematic safe removal of materials. Team lifting and carrying 	Cape cod Cape cod Cape cod Cape cod Cape cod Cape cod SSE SSE SSE SSE SSE SSE SSE S

Reviewed	i by:
----------	-------

Gary Klomp

Principal Contractor's Representative

Signature

Construction Manager

Position

10 10 201A

Date

item	Job Step	Potential Hazard	Controls	Responsible Person/s
			Storage of materials in designated waste areas	554
			Regular site clean ups.	ege lod
····			 Ensure all exposed nails are removed. 	lage cod
6	Demolishing brickwork by hand	 Slips, trips, falls and accessibility. Hazardous materials. 	 Assess the site conditions and conduct a Risk Assessment before commencing. Provide "Demolition in Progress" 	Cyc Col
		 Identification of services. 	and "Restricted Access" warning signage.	Cape cod
and the state of t		Electrocution.Gas explosions.Falling objects.Exposure to dust.	 Establish a "No access area" to work areas by barricading to prevent access to the area of work. Provide a spotter where necessary. 	(age Cod
		Exposure to noise.Manual handling.Heavy lifting.	 Identify any products or materials that may contain asbestos. 	Cope (as
		 Cuts and abrasions. Proximity of other trades. 	 Identify services and ensure all electrical, gas, water and sewerage services have been isolated or safely relocated before commencing. 	(ge (is)
			Use Licensed Electrician and Plumber to isolate, disconnect and relate existing services.	Cope Cool
TO THE PERSON NAMED AND ADDRESS OF THE PERSON NAMED AND ADDRES			Use appropriate PPE – safety glasses, footwear, noise / hearing protection, dust protection [disposable], gloves, and hard hats.	SSC
			Training of "workers" in safe use of pneumatic and electrical power tools.	556
4			 Systematic safe removal of materials. 	rs€
			 Team lifting and carrying. 	555

struction Manager
Position
10, 2014 Date
2

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
			To upper floor areas provide a shute for materials into designated waste area as required. Provide a spotter where necessary.	Cox Cot
			 Monitor air quality. Provide shade cloth around work area and wet down dust as required to prevent wind borne dust. 	Cope to d
			 Storage of materials in designated waste areas Regular site clean ups. 	sse cas
7	existing roof frame and covering UV / weather exposure. Fall from height. Hazardous materials. Identification of services. Electrocution. Gas explosions. Falling objects. Exposure to dust. Exposure to noise. Manual handling. Heavy lifting. Cuts and abrasions. Proximity of other	UV / weather	Assess the site conditions including the weather and conduct a Risk Assessment before commencing.	(ge løb
ANGEL CONTRACTOR OF THE PROPERTY OF THE PROPER		Fall from height.Hazardous	 Identify any products or materials that may contain asbestos. 	(ge lod
2.		 Identification of services. Electrocution. Identify services and ensure all electrical, gas, water and sewerage services have been isolated or safely relocated 	(ge (of	
		Use Licensed Electrician and Plumber to isolate, disconnect and relate existing services.	light last	
		 Manual handling. Heavy lifting. Cuts and abrasions. Proximity of other Training of "workers" in safe working at heights. Provide "Demolition in Progress' and "Restricted Access" warning signage. 	Cose	
			Cat Cod	
		trades	Establish a "No access area" below overhead work areas by barricading to prevent access to the area of work. Provide a spotter where necessary.	Care lad
		Ensure that the scaffolding and edge protection is in place	Cage Col	

Reviewed by:	Gary Klomp
	Principal Contractor's Representative
	Signature

Construction Manager
Position

10 2012

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
			before commencing.	
			Correct use of ladder	SSE
			 Use appropriate PPE – safety glasses, footwear, noise / hearing protection, dust protection [disposable], gloves and hard hats. 	55E
	i		Training of "workers" in the safe use of hand tools and power tools.	55 E
			Systematic safe removal of materials.	554
			Team lifting and carrying.	55€
			 Provide a shute for materials into designated waste area as required. Provide a spotter where necessary. 	Cage cont
	William I		 Provide shade cloth / mesh around work area and wet down dust as required to prevent wind borne dust. 	Cyc Cod
	WATER THE TAXABLE PROPERTY OF TAXABLE PROP		 Storage of materials in designated waste areas 	S54
			Regular site clean ups.	ine and
	The second secon		Ensure all roof tarps are tied down and not weighted with tiles.	SSE cyc (od loge (od (oge lad
			Ensure materials are not stored on the roof or scaffold.	Cap lad

Reviewed by:	Gary Klomp
	Principal Contractor's Representative
	Signature

Construction Manager
Position

10, 2014 Date