

SITE SPECIFIC Risk Assessment

| Jaioi Tago | Date: | | New | ✓ | Revised | | Page | |
|--------------|-------|--|-----|---|---------|--|------|--|
|--------------|-------|--|-----|---|---------|--|------|--|

TRADE: HEATER FLUE / ROOF VENTILATOR INSTALLER

| Job No: | 7531/14 | Client: | FOGG.SHAW |
|----------|-----------------------------------|-------------|---------------|
| Address: | 13 Cairo Street South Coogee 2034 | Supervisor: | DEAN BERINGER |

| Kev: | "1" action now | "2" action ASAP | "3" action ASAP |
|------|----------------|-------------------|-------------------|
| | 1 40401111011 | _ action / to/ ti | o action / to/ ti |

Note 1: Refer to the general Safety Plan and Safe Work Method Statement.

Note 2: Safe work procedures shall be implemented for the supply and use of a *hazardous chemical / substance/s* on site that complies with the material data sheet recommendations and also complies with the requirements of WHS Regulation 2011 Chapter 3 - Part 3.2

Note 3: Review of Control Measures - If there are any tasks that may be included by way of variation to the plans or an alternative approach to the set task, it is a requirement to carry out a "specific Risk Assessment" for the tasks.

| | | Likelihood | | Result | | | | | | | |
|--|---|------------|----------|----------|-------|----------|-------|----------|--|------------------------------|------|
| Job Step / Hazard | Potential Harm | Likely | Possible | Unlikely | Major | Severe | Minor | Priority | Possible Controls | Responsible Person/s | Date |
| Access to site / work areas - Slips, trips, falls and accessibility - Access ways not clearly defined | Slips, trips and falls | | ✓ | | | ✓ | | 3 | Ensure unobstructed access to site and work areas. | Supervisor /all 'workers' | |
| Stored materials - Slips, trips, falls and accessibility - Access ways not clearly defined | Slips, trips and falls | | ✓ | | | √ | | 2 | Provide and maintain barricades to isolate material and to restrict access. Provide designated waste areas | Supervisor / all 'workers' | |
| Manual tasks | Muscle strain - back injuries and cuts Over exertion or repetitive movements | | √ | | | ✓ | | 2 | Use trained 'workers' and team lifting. Rotate 'workers' and vary tasks | Contractor / all 'workers' | |
| Exposure to noise Plant / equipment | Hearing damage | | ✓ | | | ✓ | | 2 | Isolate plant and equipment Use appropriate PPE | All 'workers' | |
| Exposure to UV light / weather - UV light - glare Extreme temperatures | Skin cancer / sun burn - Dehydration - heat stroke or fatigue Sight damage | | ✓ | | | ✓ | | 2 | Reduce exposure where possible. Monitor 'workers' condition Adequate fluid intake Use appropriate sun screen. | Contractor / all 'workers' | |

| | | Li | keliho | od | | Resul | lt | | | | |
|--|---|--------|----------|----------|-------|----------|-------|----------|--|---|------|
| Job Step / Hazard | Potential Harm | Likely | Possible | Unlikely | Major | Severe | Minor | Priority | Possible Controls | Responsible Person/s | Date |
| | | | | | | | | | Wear appropriate PPE. | | |
| Contact with o/head electrical services / point of attachment - Power lines not isolated, covered or enclosed - Working to close to electrical supply - Strong winds causing power lines to swing close to work area - Wet conditions making 'tiger tails' ineffective | Electric shock or electrocution | | ✓ | | | ✓ | | 3 | Identify that the electrical service is isolated prior to work commencing. Provide 'tiger tails' [insulation] - adequately boxed adjacent to scaffold extended an appropriate distance past the boundary | Licensed Electrical Contractor or Approved person Supervisor Contractor / all 'workers' | |
| Carry materials and tools up ramp / scaffold / roof surface - Slips, trips, falls and accessibility – Inadequate fall prevention system / work platform - Windy and or wet conditions - Slope of ramp - Pitch of roof and roofing material - Manual tasks | Slips, trips and falls from ramp / scaffold or roof surface Muscle strain - back injuries and cuts | | ✓ | | | ✓ | | 2 | Guardrails to ramp are in place - ramp surface clean and dry. Scaffold guardrails and work platform is complete - clean and dry Perimeter and edge protection / catch scaffold in place when accessing roof surface. Use trained 'workers'. Rotate 'workers' and vary tasks . Use safety harness when working from roof surface. | Contractor / all 'workers' | |
| Working at height - from roof surface Slips, trips, falls and accessibility - Inadequate fall prevention system / work platform - Pitch of roof and roofing material - | Slips, trips and falls from scaffold or roof surface - Fractures, bruises lacerations and personal injuries | | ✓ | | | ✓ | | 3 | Scaffold guard rails and work platform is complete - clean and dry Perimeter and edge protection / catch scaffold in place when working from roof surface. Use trained 'workers' | Supervisor / Contractor / all 'workers' | |

| | | Likelihood | | od | Result | | | | | | |
|---|----------------------|------------|----------|----------|--------|--------|-------|----------|---|-------------------------|------|
| Job Step / Hazard | Potential Harm | Likely | Possible | Unlikely | Major | Severe | Minor | Priority | Possible Controls | Responsible Person/s | Date |
| Gravity – overbalancing - | | | | | | | | | Train 'workers' in safe working at heights. | | |
| Windy and or wet conditions | | | | | | | | | Use safety harness when working from roof surface | | |
| | | | | | | | | | Wear appropriate footwear. | | |
| Ladder access of work areas - | Fall frame la dela s | | | | | | | | Use trained 'workers'. | Contractor / all | |
| Slips, trips, falls and accessibility - | Fall from ladder. | | ✓ | | ✓ | | | 2 | Use approved ladders. | 'workers' | |
| Gravity - overbalancing | | | | | | | | | Limit the use of ladders | | |

I / We have consulted with Cape Cod Australia Pty. Ltd. and have mutually agreed on the above procedures. This risk assessment provides details on how I / we will manage my / our work on this Cape Cod Australia Pty. Ltd. work site.

| Company Name: | Signed by: | Jaa Squaen | |
|-------------------|-----------------------|---------------------------------|--|
| | for and on behalf of: | Cape Cod Australia Pty. Limited | |
| Signed by: | | ABN: 54 000 605 407 | |
| (Contractor PCBU) | | Builder's Licence No.: 5519 | |
| ABN: | | | |
| Address: | | | |
| | | | |
| Phone: | | | |
| Fax: | | | |
| Email: | | | |