## ASBESTOS REGISTER



SITE: 7843 Wills 2 Langer Street, Banksia LAST UPDATED: 28/07/2017

JOB NUMBER CLIENT ADDRESS

| Date<br>Identified | Location of ACM                               | Туре                          | Friable /<br>Non-Friable | Quantity | Condition                                       | Assessment / Action  |
|--------------------|---|-------------------------------|--------------------------|----------|---|--|
| 25/07/2017         | Eave soffit lining                            | Asbestos cement<br>sheet      | Non-friable              | 22.5 sqm | Good/Stable Surface coated to the exposed areas | 9.5 sqm to be removed by Cape Cod as part of the contract works. Protect the retained ACM from damage during the course of the works |
| 25/07/2017         | Weatherboard cladding                         | Asbestos cement sheet         | Non-friable              | 9 sqm    | Good/Stable Surface coated to the exposed areas | To be removed by Cape Cod as part of the contract works  |
| 25/07/2017         | Gable end cladding (front)                    | Asbestos cement sheet         | Non-friable              | 15 sqm   | Good/Stable Surface coated to the exposed areas | Protect the retained ACM from damage during the course of the works  |
| 25/07/2017         | Gable end cladding<br>(rear)                  | Asbestos cement weatherboards | Non-friable              | 25 sqm   | Good/Stable Surface coated to the exposed areas | To be removed by Cape Cod as part of the contract works  |
| 25/07/2017         | Laundry wall<br>spandrel and infill<br>panels | Asbestos cement sheet         | Non-friable              | 2 sqm    | Good/Stable Surface coated to the exposed areas | Protect the retained ACM from damage during the course of the works  |

WHS-5.1-0502- Asbestos Register

Issued: February 2017

Version: 1.0

Page 1 of 2
Approved by: WHS & Human Resources Coordinator

Printed: 28/07/2017 8:31 AM

## ASBESTOS REGISTER



| 25/07/2017 | Side awning<br>outside lounge<br>room | Asbestos cement sheet                                 | Non-friable | 1 sqm    | Good/Stable<br>Surface coated to the<br>exposed areas | Protect the retained ACM from damage during the course of the works |
|------------|---------------------------------------|---|-------------|----------|---|---|
| 25/07/2017 | Front awning outside study            | Asbestos cement sheet                                 | Non-friable | 1 sqm    | Good/Stable<br>Surface coated to the<br>exposed areas | Protect the retained ACM from damage during the course of the works |
| 25/07/2017 | Laundry wall and ceiling lining       | Asbestos cement sheet                                 | Non-friable | 7.25 sqm | Good/Stable<br>Surface coated to the<br>exposed areas | Protect the retained ACM from damage during the course of the works |
| 25/07/2017 | Upstairs bathroom wall lining         | Asbestos cement sheet                                 | Non-friable | 15.5 sqm | Good/Stable<br>Surface coated to the<br>exposed areas | To be removed by Cape Cod as part of the contract works             |
| 25/07/2017 | Bedroom 3                             | Asbestos cement<br>sheet wall common<br>with bathroom | Non-friable | 7.5 sqm  | Good/Stable<br>Surface coated to the<br>exposed areas | To be removed by Cape Cod as part of the contract works             |
| 25/07/2017 | Electrical meter<br>board             | ACM   | Non-friable | 0.25 sqm | Good/Stable<br>Surface coated to the<br>exposed areas | Protect the retained ACM from damage during the course of the works |
| 25/07/2017 | Roof space                            | Asbestos cement sheet                                 | Non-friable | Unknown  | Broken pieces/Damaged                                 | Remove and dispose of the ACM                                       |

Issued: February 2017

Version: 1.0

Page 2 of 2 Approved by: WHS & Human Resources Coordinator

Printed: 28/07/2017 8:31 AM