Company [PCBU]:	New Coat Painting	Project Name/No:	All Jobs
Work Activity / Task:	PAINTER & DECORATOR	Principal Contractor:	Cape Cod Australia Pty Ltd
Prepared by:	Patrick Ryan	Date: 15/9/K4	
Signature:	P. Muyen		tool Box talk

Note: Review of Control Measures

If there are any tasks that may be included by way of variation to the plans or an alternative approach to the set task. It is a requirement to carry out a specific Risk Assessment for the tasks.

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
<b>1</b>	Access to site	<ul> <li>Slips, trips, falls and accessibility.</li> <li>UV / weather exposure.</li> </ul>	<ul> <li>Site specific induction.</li> <li>All "workers" to read the General Construction Safety Plan signage and Risk Assessment form before entering site.</li> </ul>	C
· · · · · · · · · · · · · · · · · · ·			<ul> <li>Tool box talk to highlight any WHS concerns relative to the site.</li> </ul>	
	777		<ul> <li>Ensure that the site and work place access is unobstructed.</li> </ul>	78/C
			Ensure all weather access to work areas.	B
	444		<ul> <li>Provision of designated waste areas.</li> </ul>	NEWBOT
			<ul><li>Storage of materials in designated areas.</li><li>Regular site clean ups.</li></ul>	PACTING
2	Unloading of equipment and materials	<ul><li>Manual handling injuries</li><li>Slips, trips and falls.</li></ul>	<ul> <li>Team lifting and carrying.</li> <li>Training of employees in correct lifting and carrying methods.</li> </ul>	NEWCOATC
			Unload and move the equipment and materials to a designated area to keep footpath / work place access clear.	C 1.fy
3	Setting up equipment	Manual handling injuries	Set up in a clear area and maintain a clear travel path.	NECOAT PAINTING
			Training of "workers" in the	1./hy - C

Reviewed by:	Gary Klomp	Construction Manager
	Principal Contractor's Representative	Position
	Signature	(7 /0, 2014) Date

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
		Slips, trips and falls.	setting up of ladders / trestles, electrical leads and power tools.	NOW COAT
			<ul> <li>Ensure the proper use of all safety guards provided.</li> </ul>	PAINTING
			<ul> <li>Ensure that all power tools and electrical leads have current tagging.</li> </ul>	C
			<ul> <li>Ensure that power tools are attached to a residual current device [RCD].</li> </ul>	1.h
4	Painting - external	<ul> <li>Slips, trips, falls and accessibility.</li> <li>UV / weather exposure.</li> </ul>	<ul> <li>Assess the site conditions including the weather and conduct a Risk Assessment before commencing.</li> </ul>	NEW COST
		<ul> <li>Electrocution.</li> <li>Fall from height.</li> <li>Hazardous substances.</li> <li>Exposure to dust /</li> </ul>	<ul> <li>Identify that the electrical service has been isolated and that 'tiger tails' are in place as protection from overhead wires and points of attachment before commencing.</li> </ul>	B
		<ul><li>fumes.</li><li>Manual handling.</li><li>Proximity of other "workers".</li></ul>	Establish a "No access area" below overhead work areas by barricading to prevent access to the area of work.	B/C
Valid or a management		Public access.	Ensure that guard rails to the ramp are in place and surface of the ramp is clean before commencing.	BC
			<ul> <li>Ensure that scaffolding is safe and erected by a qualified Scaffolder before commencing.</li> </ul>	B
eleministri			<ul> <li>Ensure that perimeter protection is in place [scaffolding and edge protection / working platform / toe boards] before commencing.</li> </ul>	3.
			Ensure that the edge protection to the roof surface [roof rail] and	1. Then B

Reviewed by:	Gary Klomp	Construction Manager
	Principal Contractor's Representative	Position
		17/9/2014
	Signature	Data

1.6 19/9/4

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
			level work platforms are in place before commencing work from roof surface.	MAINTING
			<ul> <li>Training of "workers" in safe working at heights, from roof surfaces and balconies.</li> </ul>	C
- Parameter			<ul> <li>Training of "workers" in safe use of plant and equipment.</li> </ul>	C
	İ		<ul> <li>Training of "workers" in safe working from step and extension ladders including workers to face ladder when climbing up and down.</li> </ul>	C
			<ul> <li>Check suitability of the ladder / trestle for purpose before use.</li> </ul>	C
	į		Check the ladder / trestle for damage / defect before use.	C
			<ul> <li>Check that the ladder / trestle is stable and is secured at the base and top before use.</li> </ul>	C
	The state of the s		<ul> <li>Limit the use of ladders as work platforms.</li> </ul>	C
***************************************			Training of "workers" in correct lifting and carrying methods.	C
with			Ensure that the correct lifting and carrying techniques are used at all times.	C
			Rotate "workers" and vary tasks performed.	C
Popular Company			Provide MSDS for hazardous substances – paint / thinners / solvents.	B
77.57			Training of "workers" in the safe handling / mixing and use of paints and stains.	
	1		<ul> <li>Wear appropriated PPE - hat, long sleeves, sun screen,</li> </ul>	C/ fly

Reviewed by:	Gary Klomp	Construction Manager
	Principal Contractor's Representative	Position
	Signature	17 10 2014 Date
	15/9/14	

item	Job Step	Potential Hazard	Controls	Responsible Person/s
			sunglasses and fluids and reduce exposure where possible.  • Use appropriate PPE – safety glasses, footwear, dust / fume protection [disposable], gloves.  • Storage of materials in	PAINTING
			designated areas.  Maintain a clean and tidy work area.	1. hunc
5	Painting - internal	<ul><li>Slips, trips, falls and accessibility</li><li>Fall from height</li></ul>	Assess the site conditions and conduct a Risk Assessment before commencing.	NEW COAT R PAINTING
1		<ul> <li>Hazardous substances</li> <li>Exposure to dust /</li> </ul>	<ul> <li>Training of "workers" in safe working at heights including over internal stairwells.</li> </ul>	C
neget woman.		fumes  Manual handling	<ul> <li>Training of "workers" in correct lifting and carrying methods.</li> </ul>	C
7		Proximity of other     "workers".	<ul> <li>Ensure that the correct lifting and carrying techniques are used at all times.</li> </ul>	C
			<ul> <li>Rotate "workers" and vary tasks performed.</li> </ul>	C
			<ul> <li>Provide MSDS for hazardous substances – paint / thinners / solvents.</li> </ul>	B
			Training of "workers" in the safe handling / mixing and use of paints and stains	C
			Use appropriate PPE – safety glasses, footwear, dust / fume protection [disposable], gloves.	C
			Ensure that adequate lighting and ventilation is available.	B/C
			Training of "workers" in safe     working from step and extension     ladders including workers to face	1. fy

Reviewed by:	Gary Klomp	Construction Manager
	Principal Contractor's Representative	Position
		· · · · · · · · · · · · · · · · · · ·
		17/10/2014
	Signature	Date 1

1- Ayon 15/9/14

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
			ladder when climbing up and down.	REW COAT PAINTING
			Check suitability of the ladder / trestle for purpose before use.	C
			Check the ladder / trestle for damage / defects before use.	C
			Check that the ladder / trestle is stable and secured at base and top before use.	C
			<ul> <li>Limit the use of ladders as work platforms.</li> </ul>	
			<ul> <li>Training of "workers" in the safe use of plant and equipment.</li> </ul>	C
			<ul> <li>Storage of materials in designated and well ventilated areas.</li> </ul>	C
			Maintain a clean and tidy work area.	I hym

Reviewed by:	Gary Klomp	Construction Manager
	Principal Contractor's Representative	Position
		im in laid

Date

Signature 8. Ayr 15/9/14