Faulks Cement Rendering

7 ocean place ILLAWONG, NSW 2234 0407 073 668 faulksrendering@hotmail.com

Safe Work Method Statement

version 1.1

Activity / Task: Polystyrene Wall Cladding Installation

Project / Location: All Jobs

Company: Faulks Cement Rendering

4. Installation of

panel wall

cladding

accessibility.

exposure.

UV light / weather

Signed by: Paul Faulks Date: 26/08/2017

Principal Contractor: Cape Cod

Accepted by: Tara Antoniolli Date: 26/08/2017

Steps	Potential Hazards	Controls / Responsible Person(s)
1. Access to site	 Slips, trips, falls and accessibility. UV light / weather exposure. Unauthorised access 	 Site specific induction. By: Faulks Cement Rendering All "workers" to register before entering the site; to read the General Construction Safety Plan signage; and to read the Site Specific Risk Assessment form. By: Faulks Cement Rendering & Worker Tool box talk to highlight any WHS concerns relative to the site. By: Faulks Cement Rendering Ensure that the site and work place access is unobstructed. By: Principal Contractor & Faulks Cement Rendering & Worker Ensure all weather access to work areas. By: Principal Contractor Provision of designated waste areas. By: Principal Contractor Storage of materials in designated areas. By: Faulks Cement Rendering & Worker Provide and maintain barricades to all materials stored on footpath and on site. By: Principal Contractor & Faulks Cement Rendering & Worker Regular site clean ups. By: Principal Contractor Maintain site security controls, such as fencing/ locks/ gates By: Worker
Unloading plant, equipment and tools	•	 Team lifting and carrying. By: Worker Training of "workers" in correct lifting methods. By: Faulks Cement Rendering Unload and move equipment to designated area to keep footpath / work place access clear. By: Faulks Cement Rendering Ensure clear path and adequate work area By: Worker
3. Setting up equipment / transportation of material and equipment to work areas	 Manual task injuries Slips, trips and falls. Proximity of other "workers". Public access. Electricity Work at height 	 Set up in a clear area and maintain a clear travel path. By: Faulks Cement Rendering Training of "workers" in setting up of electrical leads and power tools. By: Faulks Cement Rendering Ensure the proper use of all safety guards provided. By: Faulks Cement Rendering & Worker Ensure that all electrical power tools and electrical leads have current tagging and Residual Current Devices are supplied By: Faulks Cement Rendering Ensure that all power tools are attached to a residual current device [RCD] and electrical tagging is current By: Worker Inspect all equipment prior to use and ensure in good working condition By: Worker Ensure that the perimeter protection is in place before commencing. [Scaffold as working platform] By: Principal Contractor & Faulks Cement Rendering & Worker Identify that the electrical service has been isolated and that 'tiger tails' are in place as protection from overhead wires and points of attachment before commencing installation work. By: Principal Contractor Ensure that scaffolding is safe and erected by a qualified Scaffolder By: Principal Contractor Ensure that the guard rails to the ramp are in place and that the surface of the ramp is clean before commencing. By: Worker

• Slips, trips, falls and • Assess the site conditions including the weather and conduct a Site Specific Risk Assessment

Rendering & Worker

where possible. By: Worker

before commencing installation work; report all unsafe conditions to Supervisor By: Faulks Cement

• Wear appropriated PPE - hat, long sleeves, sun screen, sunglasses and fluids and reduce exposure

- Electrocution.
- Fall from height.
- Manual task injuries
- Exposure to dust.
- Exposure to noise.
- Proximity of other "workers".
- Public access.
- Ensure that the perimeter protection is in place before commencing. [Scaffold as working platform] By: Faulks Cement Rendering
- Ensure that the edge protection to the roof surface [roof rail] and level work platforms are in place before commencing work from roof surface. By: Worker
- Training of "workers" in safe working at heights and safe movement on roof. By: Faulks Cement Rendering
- Training of "workers" in correct lifting methods. By: Faulks Cement Rendering
- Ensure that correct lifting and carrying techniques are used at all times. By: Faulks Cement Rendering
- Team lifting and carrying -limiting weights to manageable sizes. By: Faulks Cement Rendering
- Ensure "workers" have safety glasses, noise protection, dust protection [disposable], protective footwear and gloves. By: Faulks Cement Rendering & Worker
- Provide SDS for hazardous substances polystyrene. By: Faulks Cement Rendering
- Provide appropriate containment and disposal of waste polystyrene. By: Principal Contractor & Faulks Cement Rendering
- Training of "workers" in the safe handling and use of polystyrene. By: Faulks Cement Rendering
- Training of "workers" in the safe use of power tools. By: Faulks Cement Rendering
- Ensure all power tools have working safety guards. By: Faulks Cement Rendering
- Storage of materials in designated areas. By: Worker
- Maintain a clean and tidy work area. By: Worker

- Site clean up on completion of work
- Manual task injuries
- Exposure to dust
- Exposure to hazardous substances
- Remove any temporary barricades if no longer required By: Worker
- Place all rubbish / debris in designated waste storage area By: Faulks Cement Rendering & Worker
- Leave site / work area in a clean and tidy condition By: Worker
- Ensure correct manual handling technique, team lifts and use of mechanical aid where possible By:
 Worker

Person responsible for ensuring compliance with SWMS: Person responsible for reviewing SWMS control measures: P & L Faulks Cement Leading Hands Paul Faulks

Document Updated: 26/08/2017