On-Point Carpentry & Joinery

49 Cropton Street JORDAN SPRINGS, NSW 2747 0422 698 035 daniel.mcgaw@hotmail.com

Safe Work Method Statement

version 1.1

Activity / Task: Fixout Carpenter

Project / Location: All Jobs

Company: On-Point Carpentry & Joinery

Signed by: Daniel McGaw Date: 21/06/2017

Principal Contractor: Cape Cod

• Provide MSDS for hazardous substances – medium density fibre board [MDF] and chemically

Training of "workers" in the safe handling and use of medium density fibre board [MDF] and

treated timber products. By: On-Point Carpentry & Joinery

chemically treated timber products. By: On-Point Carpentry & Joinery

Accepted by: Tara Antoniolli Date: 22/06/2017

Steps	Potential Hazards	Controls / Responsible Person(s)
. Access to site	 Slips, trips, falls and accessibility. UV light / weather exposure. 	 Site specific induction. By: On-Point Carpentry & Joinery All "workers" to register before entering the site; to read the General Construction Safety Plan signage; and to read the Site Specific Risk Assessment form. By: On-Point Carpentry & Joinery Tool box talk to highlight any WHS concerns relative to the site. By: On-Point Carpentry & Joinery Ensure that the site and work place access is unobstructed. By: Principal Contractor Ensure all weather access to work areas. By: Principal Contractor & On-Point Carpentry & Joinery Provision of designated waste areas. By: Principal Contractor Storage of materials in designated areas. By: On-Point Carpentry & Joinery Regular site clean ups. By: Principal Contractor
. Unloading of tools and equipment		 Team lifting and carrying. By: On-Point Carpentry & Joinery Training of "workers" in correct lifting and carrying methods. By: On-Point Carpentry & Joinery Unload and move the equipment / tools to a designated area to keep footpath / work place access clear. By: On-Point Carpentry & Joinery
. Setting up plant and equipment	 Manual task injuries Slips, trips and falls. Proximity of other "workers". Public access. 	 Set up in a clear area and maintain a clear travel path. By: On-Point Carpentry & Joinery Training of "workers" in the setting up of ladders / trestles, electrical leads and power tools. By: On-Point Carpentry & Joinery Ensure the proper use of all safety guards provided. By: On-Point Carpentry & Joinery Ensure that all power tools and electrical leads have current tagging. By: On-Point Carpentry & Joinery Ensure that power tools are attached to a residual current device [RCD]. By: On-Point Carpentry & Joinery
. Ground floor - fixout	 Slips, trips, falls and accessibility. Electrocution. Fall from height. Hazardous substances. Exposure to dust. Manual task injuries Proximity of other "workers". Public access. 	 Assess the site conditions and conduct a Site Specific Risk Assessment before commencing. By: On-Point Carpentry & Joinery Identify location of electrical, gas and water services By: On-Point Carpentry & Joinery Identify that the electrical and gas service have been isolated or safely recommissioned before commencing work. By: On-Point Carpentry & Joinery Ensure that all exposed openings and voids in the floor are guard railed or covered. By: On-Point Carpentry & Joinery Training of "workers" in safe working from step ladders. By: On-Point Carpentry & Joinery Check the ladder / trestles for damage / defect before use. By: On-Point Carpentry & Joinery Check that the trestle work platform is stable before use. By: Principal Contractor Limit the use of ladders as work platforms. By: On-Point Carpentry & Joinery Training of "workers" in correct lifting and carrying methods. By: On-Point Carpentry & Joinery Ensure that the correct lifting and carrying techniques are used at all times. By: On-Point Carpentry & Joinery

- Use appropriate PPE safety glasses, footwear, dust protection [disposable] and gloves. By: On-Point Carpentry & Joinery
- Storage of materials in designated areas. By: On-Point Carpentry & Joinery
- Maintain a clean and tidy work area. By: Principal Contractor

- Upper floor fixout
- Slips, trips, falls and accessibility.
- Electrocution.
- Fall from height.
- Hazardous substances.
- Exposure to dust.
- Manual task injuries
- Proximity of other "workers
- Assess the site conditions and conduct a Site Specific Risk Assessment before commencing. By:
 On-Point Carpentry & Joinery
- Ensure that the temporary guard rails or permanent handrails are in place to the internal stairwell
 and upper floor external balconies before commencing. By: On-Point Carpentry & Joinery
- Ensure that all exposed openings and voids in the floor are guard railed or covered. By: On-Point Carpentry & Joinery
- Training of "workers" in safe working at heights including over internal stairwells and from external balcony decks. By: On-Point Carpentry & Joinery
- Identify location of electrical service and that the service has been isolated or safely recommissioned before commencing work. By:
- Team lifting and carrying of solid core doors and vanity units. By: On-Point Carpentry & Joinery
- Training of "workers" in correct lifting and carrying methods. By: On-Point Carpentry & Joinery
- Ensure that the correct lifting and carrying techniques are used at all times. By: On-Point Carpentry & Joinery
- Training of "workers" in safe working from step ladders. By: On-Point Carpentry & Joinery
- Check the ladder or trestles for damage / defect before use. By: On-Point Carpentry & Joinery
- Check that the trestle work platform is stable before use. By: On-Point Carpentry & Joinery
- Limit the use of ladders as work platforms. By: On-Point Carpentry & Joinery
- Provide MSDS for hazardous substances medium density fibre board [MDF] and chemically treated timber products. By: On-Point Carpentry & Joinery
- Training of "workers" in the safe handling and use of medium density fibre board [MDF] and chemically treated timber products. By: On-Point Carpentry & Joinery
- Use appropriate PPE safety glasses, footwear, dust protection [disposable] and gloves. By: On-Point Carpentry & Joinery
- Storage of materials in designated areas. By: On-Point Carpentry & Joinery
- Maintain a clean and tidy work area. By:

- 6. Carry materials up ramp External access to upper floor
- Slips, trips, falls and
 accessibility.
- Fall from height.
- Electrocution.
- Manual task injuries
- Proximity of other "workers".
- Assess the site conditions including the weather and conduct a Site Specific Risk Assessment before commencing work. By: On-Point Carpentry & Joinery
- Identify that the electrical service has been isolated and that 'tiger tails' are in place as protection
 from overhead wires and points of attachment before commencing. By: On-Point Carpentry &
 Joinery
- Ensure that the guard rails to the ramp are in place and that the surface of the ramp is clean before commencing. By: On-Point Carpentry & Joinery
- Ensure that the perimeter protection is in place [scaffolding and edge protection] and level walk platforms are in place before accessing work from roof surface. By: On-Point Carpentry & Joinery
- Ensure that the edge protection to the roof surface [roof rail] and level work platforms are in place before accessing the upper floor level from roof surface. By: On-Point Carpentry & Joinery
- Ensure that the perimeter protection [temporary guard rail] is in place to balconies before commencing. By: On-Point Carpentry & Joinery
- Training of "workers" in safe working at heights. By: On-Point Carpentry & Joinery

- 7. Site clean up on completion of work
- Manual task injuries
- Exposure to dust
- Exposure to hazardous substances
- Remove any temporary barricades if no longer required By: Principal Contractor
- Place all rubbish / debris in designated waste storage area By: On-Point Carpentry & Joinery
- Leave site / work area in a clean and tidy condition By:

Person responsible for ensuring compliance with SWMS: Person responsible for reviewing SWMS control measures: Daniel Mcgaw Daniel Mcgaw