ASBESTOS REGISTER



SITE: 7752 Warner.Park 53 Gipps Street, Paddington LAST UPDATED: 23/02/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Туре	Friable / Non-Friable	Quantity	Condition	Assessment / Action
12/01/2017	Eave soffit lining	Asbestos cement sheet	Non-friable	3.5 sqm	Good/stable Painted	To be removed as part of the contract works, protect the retained ACM from damage during the course of the works
12/01/2017	Front porch/balcony soffit lining	Asbestos cement sheet	Non-friable	5 sqm	Good/stable Painted	To be removed as part of the contract works
12/01/2017	Front alcove ceiling lining	Asbestos cement sheet	Non-friable	1 sqm	Good/stable Painted	Protect the retained ACM from damage during the course of the works
12/01/2017	Store wall and ceiling lining	Asbestos cement sheet	Non-friable	4 sqm	Good/stable Painted	To be removed as part of the contract works
12/01/2017	Laundry ceiling lining	Asbestos cement sheet	Non-friable	2.25 sqm	Good/stable Painted	To be removed as part of the contract works

ASBESTOS REGISTER



12/01/2017	Under staircase	Asbestos cement	Non-friable	2 sqm	Good/stable	Protect the retained ACM from
	lining	sheet			Painted	damage during the course of the
						works

WHS-5.1-0502- Asbestos Register

Issued: February 2017 Version: 1.0