Fresh Start

Safe Work Method Statement

Project / Location: All Jobs

version 1.0

Activity / Task: Site Cleaner - Manual

Company: Fresh Start

Signed by: Chris Moerman Date: 09/11/2015

Principle Contractor: Cape Cod

Accepted by: Tara Antoniolli Date: 15/07/2016

Steps	Potential Hazards	Controls / Responsible Person(s)
эсерз	rotential nazarus	Controls / Responsible Ferson(s)
1. Access to site	 Slips, trips, falls and accessibility UV / weather exposure. 	 Site specific induction. By: Fresh Start All "workers" to read the General Construction Safety Plan signage and Risk Assessment form before entering site. By: Fresh Start Tool box talk to highlight any WHS concerns relative to the site. By: Fresh Start Ensure that the site and work place access is unobstructed. By: Fresh Start Wear appropriated PPE - hat, long sleeves, sun screen, sunglasses and fluids and reduce exposure where possible. By: Fresh Start Provision of designated waste areas. By: Principle Contractor Storage of materials in designated areas. By: Fresh Start
2. Unloading plant, equipment and tools	 Public access Manual handling injuries Slips, trips and falls. Proximity of other "workers". Public access. 	 Identify traffic management requirements By: Principle Contractor Provide as a minimum, low level basic requirements signage and barriers / witches hats. By: Principle Contractor Provide a spotter where necessary. By: Fresh Start Unload and move the equipment to designated area to keep footpath / work place access clear. By: Fresh Start Team lifting and carrying. By: Fresh Start Training of "workers" in correct lifting and carrying methods. By: Fresh Start
3. Setting up equipment	 Manual handling injuries. Slips, trips and falls. Failure of mechanic to plant. Proximity of other "workers". Public access. 	 Set up in a clear area and maintain a clear and barricaded travel path. By: Fresh Start Training of "workers" in setting up of safe work travel areas. By: Fresh Start Ensure the proper use of all safety guards provided to plant and equipment. By: Fresh Start Plant to be fully maintained and serviced. By: Fresh Start
4. Site Clean	 Slips, trips, falls and accessibility. UV / weather exposure. Electrocution. Fall from height. Manual handling injuries. Exposure to dust. Exposure to noise. Proximity of other "workers". Public access. 	 Assess the site conditions including the weather and conduct a Risk Assessment before commencing installation work. By: Fresh Start Identify any products or materials that may contain asbestos. By: Principle Contractor Identify services and make sure all the electrical, gas, water and sewerage services have been isolated or safely relocated before commencing work. By: Principle Contractor & Fresh Start Use Licensed Electrician and Plumber to isolate, disconnect and relate existing services By: Principle Contractor Wear appropriated PPE - hat, long sleeves, sun screen, sunglasses and fluids and reduce exposure where possible By: Fresh Start Training of "workers" in safe working and safe movement on site. By: Fresh Start Training of "workers" in correct lifting and carrying methods. By: Fresh Start Ensure that correct lifting and carrying techniques are used at all times By: Fresh Start Team lifting and carrying -limiting weights to manageable sizes. By: Fresh Start Ensure workers have safety glasses, noise protection, dust protection [disposable], protective footwear. By: Fresh Start Training of "workers" in safe use of power tools. By: Fresh Start

• Ensure all power tools have working safety guards. By: Fresh Start

• Maintain a clean and tidy work area. By: Fresh Start

Person responsible for ensuring compliance with SWMS: Person responsible for reviewing SWMS control measures:

Document Updated: 15/07/2016