ASBESTOS REGISTER



SITE: 7782 Bastian 19 Redman Avenue, Seaforth LAST UPDATED: 23/02/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Туре	Friable / Non-Friable	Quantity	Condition	Assessment / Action
24/01/2017	Eave and porch soffit lining	Asbestos cement sheet	Non-friable	21.5 sqm	Good/stable Painted	2.5 sqm to be removed as part of the contract works, protect the retained ACM from damage during the course of the works
24/01/2017	Bedroom 4 ceiling lining	Asbestos cement sheet	Non-friable	10.5 sqm	Good/stable Painted	Remove and dispose of ACM as part of the contract works
24/01/2017	Laundry ceiling lining	Asbestos cement sheet	Non-friable	5 sqm	Good/stable Painted	Protect the retained ACM from damage during the course of the works
24/01/2017	Manhole cover	Asbestos cement sheet	Non-friable	0.5 sqm	Good/stable Painted	Remove and replace during the construction works
24/01/2017	Disused ceiling mounted HWS	ACM	Non-friable	Unknown	Unknown	Remove and dispose of the disused hot water system with ACM
24/01/2017	Electrical meter board	ACM	Non-friable	0.25 sqm	Good/stable	Protect the retained ACM from damage during the course of the works

WHS-5.1-0502- Asbestos Register

Page 1 of 2

Issued: February 2017

Version: 1.0

Approved by: WHS & Human Resources Coordinator
Printed: 23/02/2017 3:00 PM

ASBESTOS REGISTER



WHS-5.1-0502- Asbestos Register

Issued: February 2017 Version: 1.0 Approved by: WHS & Human Resources Coordinator Printed: 23/02/2017 3:00 PM