ASBESTOS REGISTER



SITE: 7805 Miller.Windeyer 20 Tantallon Road, Lane Cove West LAST UPDATED: 23/02/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Туре	Friable / Non-Friable	Quantity	Condition	Assessment / Action
02/02/2017	Sunroom northern wall lining	Asbestos cement sheet	Non-friable	4.8 sqm	Good/stable Painted	Protect the retained ACM from damage during the course of the works
02/02/2017	Disused ceiling mounted HWS	ACM	Non-friable	Unknown	Unknown	Remove and dispose of the disused hot water system with ACM