ASBESTOS REGISTER



SITE: 7786 Vallis 9 Hilda Road, Baulkham Hills LAST UPDATED: 29/03/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Туре	Friable / Non-Friable	Quantity	Condition	Assessment / Action
26/10/2016	Eave soffit lining	Asbestos cement sheet	Non-friable	Unknown	Good/stable	Protect the retained ACM from damage during the course of the works
26/10/2016	Gable end lining	Asbestos cement sheet	Non-friable	Unknown	Good/stable	Protect the retained ACM from damage during the course of the works
26/10/2016	Front porch	Asbestos cement sheet	Non-friable	Unknown	Good/stable	Protect the retained ACM from damage during the course of the works
26/10/2016	WC	Asbestos cement wall lining	Non-friable	Unknown	Good/stable	Protect the retained ACM from damage during the course of the works
26/10/2016	Bathroom	Asbestos cement wall lining	Non-friable	Unknown	Good/stable	Protect the retained ACM from damage during the course of the works

ASBESTOS REGISTER



26/10/2016	Electrical meter	Asbestos cement	Non-friable	Unknown	Good/stable	Protect the retained ACM from
	board	sheet				damage during the course of the
						works

WHS-5.1-0502- Asbestos Register

Issued: February 2017 Version: 1.0