| Company [PCBU]: | | Project Name/No: | |
|-----------------------|---|--|----------------------------|
| Work Activity / Task: | Demolition and removal of materials by hand | Principal Contractor: | Cape Cod Australia Pty Ltd |
| Prepared by: | LEN DUNN | Date: | 03.04.2015. |
| Signature: | Du | Note: Sign off to be provided at Tool Box talk | |

Note: Review of Control Measures -

If there are any tasks that may be included by way of variation to the plans or an alternative approach to the set task. It is a requirement to carry out a specific Risk Assessment for the tasks.

| Task/Problem | Hazard | Lik | eliho | ood | F | Resu | llt | | Possible Control | Action By | Date |
|-----------------------------------|---------|--------|----------|----------|-------|--------|-------|----------|-------------------------------------|--------------------------|------|
| Variation to plan Change of Brief | Unknown | Likely | Possible | Unlikely | Major | Severe | Minor | Priority | Tool Box Talk Work Method Statement | Contractor Supervisor | |
| | | ٧ | | | ٧ | | | 1 | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |

| Item | Job Step | Potential Hazard | Controls | Responsible Person/s |
|------|----------------|---|--|-------------------------|
| 1 | Access to site | Slips, trips, falls and accessibility. UV / weather exposure. | Site specific induction. All "workers" to read the General Construction Safety Plan signage and Risk Assessment form before entering site. Tool box talk to highlight any WHS concerns relative to the site. | LEBOUNN |
| | | | Ensure that site and work place access is unobstructed. | CADECOD. |
| | | | Ensure all weather access to work areas. | CAPE COD. |
| | | | Wear appropriated PPE - hat, long sleeves, sun screen, sunglasses and fluids and | L&BOUNN. |

| Reviewed by: | | | |
|--------------|--------------|----------------------------|---|
| | Principal Co | ontractor's Representative | _ |
| | | | |
| | Signa | nature | |

Construction Manager Position

1314/15 Date

| Item | Job Step | Potential Hazard | Controls | Responsible Person/s |
|------|---|---|--|--|
| | | | reduce exposure where possible. Provision of designated waste areas. Storage of materials in designated areas. Regular site clean ups. | CAPE COD. L&BDUNN. L&BDUNN. |
| 2 | Unloading plant, equipment and tools | Manual handling injuries Slips, trips and falls. Proximity of other "workers". Public access. | Team lifting and carrying. Training of "workers" in correct lifting and carrying methods. Unload and move the equipment to designated area to keep footpath / work place access clear. | L88 DUNN L88 DUNN |
| 3 | Setting up equipment | Manual handling injuries Slips, trips and falls. Proximity of other "workers". Public access. | Set up in a clear area and maintain a clear travel path. Training of "workers" in setting up of electrical leads and power tools and pneumatic tools. Ensure proper use of all safety guards provided. Ensure that all power tools and electrical leads have current tagging. Ensure that all power tools are attached to a residual current device [RCD]. | L&B DUNN. L&B DUNN. L&B DUNN. L&B DUNN. |
| 4 | Stripping of external cladding | Slips, trips, falls and accessibility UV / weather exposure Electrocution Hazardous materials Exposure to dust Exposure to noise | Assess the site conditions and conduct a Risk Assessment before commencing. Identify that the electrical service has been isolated and that 'tiger tails' are in place as protection from overhead wires and points of attachment before commencing installation work. Provide "Demolition in | L&B DUNN. |

Reviewed by: Contractor's Representative

| Item | Job Step | Potential Hazard | Controls | Responsible Person/s |
|------|---|---|--|--|
| | | Manual handling Cuts and abrasions. Proximity of other "workers". Public access. | Progress" and "Restricted Access" warning signage. Establish a "No access area" to work areas by barricading to prevent access to the area of work. Provide a spotter where necessary. Identify any products or materials that <i>may</i> contain asbestos. Ensure that the scaffolding is safe and erected by a qualified Scaffolder before commencing. Ensure that the scaffolding and edge protection is in place before commencing. Correct use of ladder. Use appropriate PPE – safety glasses, footwear, noise / hearing protection, dust protection [disposable], gloves and hard hats. Training of "workers" in the safe use of hand tools and power tools. Systematic safe removal of materials. Team lifting and carrying. Storage of materials in designated waste areas Regular site clean ups. Ensure materials are not stored on roof surface or scaffold. | L&BDUNN. L&BDUNN. |
| 5 | Demolishing of ground floor by hand | Slips, trips, falls and accessibility. UV / weather exposure. Hazardous materials. | Assess the site conditions and conduct a Risk Assessment before commencing. Identify any products or materials that <i>may</i> contain asbestos. | L&B DUNN. |

Reviewed by: Frincipal Contractor's Representative

| Item | Job Step | Potential Hazard | Controls | Responsible Person/s |
|------|--------------------------|---|---|-------------------------------------|
| | | Identification of services. Electrocution. Gas explosions. Falling objects. Exposure to dust. Exposure to noise. Manual handling. | Identify services and make sure all electrical, gas, water and sewerage services have been isolated or safely relocated before commencing. Use Licensed Electrician and Plumber to isolate, disconnect and relate existing services. Provide "Demolition in | L&BDUNN. L&BDUNN. |
| | | Heavy lifting. Cuts and abrasions. Proximity of other "workers". Public access. | Progress" and "Restricted Access" warning signage. • Establish a "No access area" to work areas by barricading to prevent access to the area of work. Provide a spotter where necessary. | L&B DUNN. |
| | | | Monitor air quality. Ensure that all exposed openings and voids in the floor are guard railed or covered. | CAPE COD. |
| | | | Use appropriate PPE – safety glasses, footwear, noise / hearing protection, dust protection [disposable], gloves, and hard hats. | L&B DUNN. |
| | | | Training of "workers" in the safe use of pneumatic and electrical power tools. | L&BDUNN. |
| | | | Systematic safe removal of materials. | L&BOWN. |
| | | | Team lifting and carrying.Provide shade cloth around | L&B OUNN. |
| | | | work area and wet down dust as required to prevent wind borne dust. | CARE COD. |
| | | | Storage of materials in designated waste areas | L&B DUNN. |
| | - | | Regular site clean ups. | LEB DUNN |
| | | | Ensure all exposed nails are removed. | L&B DUNN. L&B DUNN. L&B DUNN. |
| 6 | Demolishing brickwork by | Slips, trips, falls | Assess the site conditions and conduct a Risk Assessment | L&B DUNN. |

Reviewed by: Principal Contractor's Representative

| Item | Job Step | Potential Hazard | Controls | Responsible Person/s |
|------|----------|---|---|-------------------------|
| | hand | and accessibility. • Hazardous | before commencing. • Provide "Demolition in | LEBANN. |
| | | materials. • Identification of | Progress" and "Restricted Access" warning signage. | LES PORITA |
| | | services. • Electrocution. • Gas explosions. • Falling objects. | Establish a "No access area" to work areas by barricading to prevent access to the area of work. Provide a spotter where necessary. | L&BOUNN |
| | | Exposure to dust.Exposure to noise.Manual handling. | Identify any products or materials that may contain asbestos. | LEBOUNN |
| | | Heavy lifting. Cuts and abrasions. Proximity of other | Identify services and ensure all electrical, gas, water and sewerage services have been isolated or safely relocated before commencing. | LX B DUNN. |
| | | trades. | Use Licensed Electrician and Plumber to isolate, disconnect and relate existing services. | L&B DUNN. |
| | | | Use appropriate PPE – safety glasses, footwear, noise / hearing protection, dust protection [disposable], gloves, and hard hats. | L&B DUNN. |
| | | | Training of "workers" in safe use of pneumatic and electrical power tools. | L&BDUNN. |
| | | | Systematic safe removal of materials. | L&BDUNN. |
| | | | Team lifting and carrying. | LEBOUND. |
| | | | To upper floor areas provide a shute for materials into designated waste area as required. Provide a spotter where necessary. | CAPE COD. |
| - | | | Monitor air quality. Provide shade cloth around work area and wet down dust as required to prevent wind borne dust. | CAPE CED. |
| | | | Storage of materials in designated waste areas | LEBOUNN. |

Reviewed by: Principal Contractor's Representative

| Item | Job Step | Potential Hazard | Controls | Responsible Person/s |
|------|--|--|---|-------------------------|
| | | | Regular site clean ups. | L&B DUNN. |
| 7 | Stripping of existing roof frame and covering | Slips, trips, falls and accessibility. UV / weather exposure. Fall from height. Hazardous materials. Identification of | Assess the site conditions including the weather and conduct a Risk Assessment before commencing. Identify any products or materials that <i>may</i> contain asbestos. Identify services and ensure | L&BOUN, |
| | | services. • Electrocution. • Gas explosions. | all electrical, gas, water and sewerage services have been isolated or safely relocated before commencing. | |
| | | Falling objects.Exposure to dust.Exposure to noise. | Use Licensed Electrician and Plumber to isolate, disconnect and relate existing services. | L88 out. |
| | | Manual handling. Heavy lifting. | Training of "workers" in safe working at heights. | CAPE COS. |
| | | Cuts and abrasions. | Provide "Demolition in Progress" and "Restricted Access" warning signage. | CAPE COS. |
| | | Proximity of other trades | Establish a "No access area" below overhead work areas by barricading to prevent access to the area of work. Provide a spotter where necessary. | L&B DUNN. |
| | | | Ensure that the scaffolding and edge protection is in place before commencing. | L&B DUNN. |
| | | | Correct use of ladder | L&BOWN. |
| | | | Use appropriate PPE – safety glasses, footwear, noise / hearing protection, dust protection [disposable], gloves and hard hats. | LEBANN. |
| | | | Training of "workers" in the safe use of hand tools and power tools. | LEBONN. |
| | | | Systematic safe removal of materials. | L&B DUNN. |
| | | | Team lifting and carrying. | L& 3 DUNN' |
| | | | Provide a shute for materials | L&B DUNN. |

Reviewed by:

Principal Contractor's Representative

SAFE WORK METHOD STATEMENT [cont.]

Page 7 of 7

| Item | Job Step | Potential Hazard | Controls | Responsible Person/s |
|------|----------|------------------|--|-------------------------|
| | | | into designated waste area as required. Provide a spotter where necessary. | L8 B DUNN. |
| | | | Provide shade cloth / mesh around work area and wet down dust as required to prevent wind borne dust. | CAPE COD. |
| | | | Storage of materials in designated waste areas | LEB DUNN. |
| | | | Regular site clean ups. | LES DUNN. |
| | | | Ensure all roof tarps are tied down and not weighted with tiles. | L&BOUNN. |
| | | | Ensure materials are not stored on the roof or scaffold. | LEBOUN. |

Reviewed by: Can Concordant Principal Contractor's Representative