Company Name:	FAULKS CEMENT RENDERING PL	Project Name/No:	ALL SITY
Work Activity / Task:	SCAFFOLDER - ERECTION	Principal Contractor:	Cape Cod Australia Pty. Ltd.
Prepared by:	Pau Faucus	Date: 03-02-14	
Signature:	A7>	Note: Sign off to be provided at Tool Box talk	

Note: Review of Control Measures - If there are any tasks that may be included by way of variation to the plans or an alternative approach to the set task, it is a requirement to carry out a "Specific Risk Assessment" for the tasks.

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
1	Access to site.	 Slips, trips, falls and accessibility. UV light / weather exposure. 	 Site specific induction. All "workers" to read the General Construction Safety Plan signage and Risk Assessment form before entering site. Tool box talk to highlight any WHS concerns relative to the site. Ensure that the site and work place access is unobstructed. Ensure all weather access to work areas. Wear appropriated PPE - hat, long sleeves, sun screen, sunglasses, and fluids and reduce exposure where possible. Storage of materials /plant in designated areas. Provide and maintain barricades to all materials stored on footpath and on site. 	PF PF PF CC PF
			 Regular site clean ups. 	CC

Reviewed by: Gary Klomp

On behalf of Cape Cod

construction Manager

Position

Date

Page 2 of 5 v1.13

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
2	Unloading tools, ladders	Manual task injuriesSlips, trips and falls.	Team lifting and carrying.Training of "workers" in correct lifting	PF PF
	and handling of scaffold components	Proximity of other "workers".Public access.	 and carrying methods. Unload and move the tools, ladders and scaffold components to a designated storage and stacking area to keep footpath / work place access clear. 	PF
3	Setting up	Manual task injuriesSlips, trips and falls.Falls from height.	Assess the site conditions including the weather and conduct a Site Specific Risk Assessment before commencing.	PP
		Uneven site.UV / weather exposure.	Set up in a clear area and maintain a clear travel path.	b E
		 Proximity of other "workers". 	 Identify the location of the electrical, sewer and stormwater services. 	CC
		Public access.	Identify that the electrical service has been isolated or safely recommissioned before commencing work.	CC PF
			All scaffolding is to be erected by WorkCover NSW certified Scaffolders.	
			Training of "workers" in the setting up of ladders, electrical equipment and use of safety harnesses.	PF
			Ensure the proper use of all safety guards and systems provided.	PR
			Ensure that all power tools and electrical leads have current tagging.	PF
			Ensure that power tools are attached to a residual current device [RCD].	PR
			Provide "Restricted Access" warning signage.	PF/CC
			 Establish a "No access area" to work areas by barricading to prevent access to the area of work. Provide a spotter where necessary. 	PF/CC
4	Erection of scaffold to 2.0m.	Slips, trips, falls and accessibility.	Assess the site conditions and conduct a Site Specific Risk Assessment before commencing.	PF

Reviewed by:	Gary	Klomp	
•		of Cape Cod	

CONSTRUCTION Manager
Position

Elatham as per GK Signature

// Date

Page 3 of 5 v1.13

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
	Passing	Fall from heights.Manual task injuries	Identify the location of the electrical, sewer and stormwater services.	C. C. PF
	scaffolding components from building level or ground.	 Sprains and strains. Cuts and abrasions. Electrocution. Exposure to noise. 	 Identify that the electrical service has been isolated and that 'tiger tails' are in place as protection from overhead wires and points of attachment before commencing. 	C.C. PF PF Cc PF Cc PF Cc
		Exposure to dust.UV / weather exposure.	Provide "Restricted Access" warning signage.	PF/CC
The state of the s		 Proximity of other "workers". Public access. 	Establish a "No access area" below overhead work areas by barricading to prevent access to the area of work. Provide a spotter where necessary.	PF/Cc
- 1			 Training of "workers" in correct lifting and carrying methods. 	PF
			 Ensure correct lifting and carrying techniques are used at all times. 	PF
			 Rotate "workers" and vary tasks performed. 	PF
			 Ensure "workers" have safety glasses, noise and dust protection, appropriate protective footwear, hard hat and gloves. 	PF
			 Training of "workers" in the safe use of power tools and equipment. 	PF
			 Ensure that all power tools have working safety guards. 	PF
			 Storage of surplus scaffold components in designated areas so not to endanger the public or other "workers". 	PF
			Maintain a clean and tidy work area. Clearly display "Saaffeld incomplete"	PF/CC PF
			 Clearly display "Scaffold incomplete" sign to incomplete scaffold at all times prior to sign off of the scaffold. 	PF
5	Continue to erect scaffold top out	 Slips, trips, falls and accessibility. Fall from heights. 	 Assess the site conditions and conduct a Site Specific Risk Assessment before commencing. 	PF
	Work from two	Manual task injuriesSprains and strains.	Identify that the electrical service has been isolated and that 'tiger tails' are	

Reviewed by: Gory Clomp
On behalf of Cape Cod

Position

Signature

Date

Page 4 of 5 v1.13

i	tem	Job Step	Potential Hazard	Controls	Responsible Person/s
		[2] plank width working platform	 Cuts and abrasions. Electrocution. Exposure to noise. Exposure to dust. UV / weather exposure. Proximity of other "workers". Public access. 	in place as protection from overhead wires and points of attachment before commencing. Provide "Restricted Access" warning signage. Establish a "No access area" below overhead work areas by barricading to prevent access to the area of work. Provide a spotter where necessary. Training of "workers" in correct lifting and carrying methods. Ensure correct lifting and carrying techniques are used at all times. Rotate "workers" and vary tasks performed. Training of "workers" in the setting up of ladders and use of safety harnesses. Ensure workers have safety glasses, noise and dust protection, appropriate protective footwear, hard hat and gloves. Training of "workers" in the safe use of power tools and equipment. Ensure that all power tools have working safety guards. Storage of surplus scaffold components in designated areas so not to endanger the public or other "workers" Maintain a clean and tidy work area. Clearly display "Scaffold incomplete" sign to incomplete scaffold at all times prior to sign off of the scaffold.	PF/CC PF/CC PF PF PF PF PF/CC PF/CC
6	Minister Personal und des des l'estre de l'estre un des déclaracións de des l'estre un des déclaracións de des	Continue to erect scaffold top out. Access to be built up with	 Slips, trips, falls and accessibility. Fall from heights Manual task injuries Sprains and strains. 	 Assess the site conditions and conduct a Site Specific Risk Assessment before commencing. Identify that the electrical service has been isolated and that 'tiger tails' are in place as protection from overhead 	PR

Reviewed by: Gay Komp
On behalf of Cape Cod

Construction Manager Position

Page 5 of 5 v1.13

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
	scaffold. Access to scaffold by ladder, balcony deck internal stair or ladder.	 Cuts and abrasions. Electrocution. Exposure to noise. Exposure to dust UV / weather exposure. Proximity of other "workers". Public access. 	wires and points of attachment before commencing. Provide "Restricted Access" warning signage. Establish a "No access area" below overhead work areas by barricading to prevent access to the area of work. Provide a spotter where necessary. Training of "workers" in correct lifting and carrying methods. Ensure correct lifting and carrying techniques are used at all times. Rotate "workers" and vary tasks performed. Ensure "workers" have safety glasses, noise and dust protection, appropriate protective footwear, hard hat and gloves. Training of "workers" in the safe use of power tools and equipment. Ensure that all power tools have working safety guards. Storage of surplus scaffold components in designated areas so not to endanger the public or "workers". Maintain a clean and tidy work area.	PF(CC PF/CC PF/CC PF PC PF PF PF PF PF
- Control of the Cont			Clearly display "Scaffold incomplete" sign to incomplete scaffold at all times prior to sign off of the scaffold.	PF
7	Site clean up on completion of work	 Manual task injuries Exposure to dust Exposure to hazardous substances- 	 Remove any temporary barricades if no longer required Place all rubbish / debris in designated waste storage area Leave site / work area in a clean and tidy condition 	PF/CC PF PF

Reviewed by: On behalf of Cape Cod

construction Marac Position

Signature