

DBWIS054 - E Safety Data Sheet EGGER OSB

| 1. IDENTIFICATION OF THE PRODUC | CT AND OF THE COMPANY |
|--|--|
| Product Name / Synonyms: | EGGER OSB 2, OSB 3 E0, OSB 3 TOP F****, OSB 3 JAS TOP, OSB 4 TOP, |
| Section Control of C | OS´Brace [®] , OS´Floor [™] (without or with termite treatment or fungicide) |
| CAS Name / No.: | N/A |
| Chemical Family: | N/A |
| Manufacturer's Name: | EGGER Holzwerkstoffe Wismar GmbH & Co. KG |
| Address: | Am Haffeld, D-23966 Wismar, Germany |
| Telephone Number: | +49 3841 301-21250 |
| FAX Number: | +49 3841 301-20222 |
| Emergency inquiry office: | +49 3841 301-0 |
| HMIS Data: | Health = 0 Flammability = 1 Reactivity = 0 Personal Protection = E |
| 2. INFORMATION ON INGREDIENTS | |
| Roundwood (mainly Softwood): | app. 88% OSB 4 TOP, OS Floor 89% OSB 2, OSB 3 E0, OSB 3 TOP F****, |
| , , | OSB 3 JAS TOP, OS Brace® |
| Water: | app. 5-7% |
| PMDI glue: | app. 5%, OSB 4 TOP, OS´Floor [™] , 3,5% OSB 2, OSB 3 E0, OSB 3 TOP F****, OSB 3 JAS TOP, OS´Brace [®] , CAS-No.: 009016-87-9 |
| Paraffin wax: | <1% |
| Permethrin 25:75 | <1%, CAS-No.: 52645-53-1 (only OS´Brace [®] , OS´Floor [™] H2 Blue) |
| WOLSIT F15 | <1%, wood protection on the base of triazolen and permethrin CAS-No.: 52645- |
| | 53-1, 107534-96-3, 60207-90-1 (only OS Brace® H3.1) |
| 3. HAZARDS IDENTIFICATION | |
| Wood dust: | Dust and splinters may cause irritations of the nose and throat, eyes and skin. |
| | Some woods may also be sensitises and some people may develop allergic |
| | dermatitis or asthma. Inhalation of wood dust may increase the risk of nasal and |
| | paranasal cancers. |
| 4. FIRST AID MEASURES | |
| Wood dust: | Swallowed: Drink a glass of water. Eye: Flush with flowing water for at least 15 |
| | minutes and if symptoms persist, seek immediate medical attention. Skin: Wash |
| | with mild soap and running water. Inhaled: Leave the dusty area. Go in a area |
| | with fresh air. |
| 5. FIRE - FIGHTINHG MEASURES | |
| Flash Point: | ≥ 200 °C |
| Fire Extinguishing Media: | Water, CO ₂ Extinguisher |
| Flammable Limits (Percent by | Lower: N/A Upper: N/A |
| Volume): | |
| Special Fire Fighting Procedures | None |
| & Equipment: | |
| Unusual Fire and Explosion | Wood dust from cutting operations, is a strong to severe explosion hazard if |
| Hazards: | dust "cloud" contacts an ignition source. Partially burned dust is especially |
| | hazardous if dispersed in air. 212 deg. F(=100°C) has been suggested as the |
| | upper temperature limit for continuous exposure of wood without risk of ignition. |
| | (Wood dust may require still a lower temperature. White pine flour as "cloud" in |
| | air requires 0,04 j minimum energy for ignition and can produce an explosion |
| | pressure of 113 psig maximum (0,8 MPa). |
| 6. ACCIDENTAL RELEASE MEASUR | ES |
| Wood dust: | Sweep or vacuum wood dust for recovery or disposal. Avoiding dusting |
| | conditions. Provide good ventilation. |

| RESPONSIBLE: | QUALITY MANAGEMENT | RELEASE DATE: | 2014-09-05 |
|----------------|------------------------|----------------|------------|
| INLOI ONSIDEE. | I QUALITI MANAGLIMLINI | INCLUAGE DATE. | 2014-03-03 |

MORE FROM WOOD. QUALITY MANAGEMENT ISO 9001



coding: revision: page: DBWIS054-E 10 2 von 3

| 7. HANDLING AND STORAGE | T = 1 |
|--|--|
| Precautions to be taken in | - The boards should be stored in dry and well ventilated areas away from |
| handling and storing: | sources of heat, flame or sparks. |
| | - Avoid hot, humid storage or contact with drying oils (spontaneous heating |
| | is possible). |
| | - Partially burned or scorched board can be hazardous to store. |
| | - Avoid generation of explosive levels of wood dust in the air. |
| | Follow good housekeeping practices; clean up areas where wood dust. Avoid the excessive accumulation of this combustible material. |
| | - Follow good hygienic practice. Wash frequently, wear clean work clothing. |
| 8. EXPOSURE CONTROL / PERSO | |
| | |
| | uld be carried out in such a way as to minimize the generation of dust, gas and ns, sawing, drilling, sanding etc should be done with equipment fitted with exhaust |
| | ust, gas and vapour at source. Hand power tools should only be used in well |
| | the spread of dust, gas and vapour. Storage and work areas should be well |
| | be cleaned at least daily and dust removed by vacuum cleaning or wet sweeping |
| method. | o clouded at loads daily and dust formerod by raddam clouding of mot encoping |
| Effects of Overexposure: | Avoid prolonged or repeating breathing of wood dust in air. Repeated |
| | exposures (even below 5 mg/m³) to certain wood dusts can produce allergic |
| | responses in a few sensitive individuals. Avoid repeated or prolonged contact |
| | with the skin. Id allergy such as conjunctivitis, retinitis, dermatitis, asthma, or |
| | bronchitis develops, it may be necessary to remove the sensitised worker from |
| | further exposure to wood dust. |
| Personal Protective Equipment (| |
| Respiratory Protection (Specify | Approved respirator under dusty conditions recommended. |
| Type): | |
| Protective gloves: | Recommended to reduce skin contact, except where moving machinery parts |
| | expose fingers to hazards. |
| Eye Protection: | Safety glasses recommended. |
| Skin Protection: | Wash with mild soap and water. Do not scratch or rub the skin if it becomes |
| 01 5 : : 5 : : | irritated. Wash work clothes regularly and separate from other clothes. |
| Other Protective Equipment: | None |
| Ventilation | The requirements of the "TA Luft" or other levelly valid level requirements to |
| Local Exhaust: | The requirements of the "TA Luft" or other locally valid legal regulations are to be kept. Due to the potential of wood dust when suspended in air, precautions |
| | should be taken to prevent sparks or other ignition sources in ventilation |
| | equipment. Use of totally enclosed motors is recommended. |
| 9. PHYSICAL AND CHEMICAL PRO | |
| physical state: | solid |
| Appearance: | yellow to brownish |
| Odour: | like softwood |
| Molecular Weight: | N/A |
| Boiling Point Deg. °C: | N/A |
| Melting Point Deg. °C: | N/A |
| Specific Gravity kg/m³: | 600 – 650 |
| Vapour Density (Air = 1) | N/A |
| Percent Volatile: | N/A |
| PH: | N/A |
| Evaporation Rate | Insoluble |
| Butyl Acetate = 1): | |
| 10. STABILITY AND REACTIVITY: | |
| Stability: | Unstable: Stable: X |
| Incompatibility (materials to | Oxidising agents and drying oils. |
| Avoid): | |
| Hazardous Decomposition | Thermal-oxidative degradation of wood produces irritating and toxic fumes and |
| Products: | gases, incl. CO, aldehydes and organic acids. |
| | |
| Hazardous Polymerisation: | Will Occur: Will Not Occur: X |
| Hazardous Polymerisation: Conditions to Avoid: | Will Occur: Will Not Occur: X Wood dust is extremely combustible. Keep in a cool, dry place away from |

MORE FROM WOOD. QUALITY MANAGEMENT ISO 9001



coding: revision: page: DBWIS054-E 10 3 von 3

| 11. TOXICOLOGICAL INFORMATION: | | |
|--|--|--|
| Oral: | Not available | |
| Dermal: | Chronic effects of Skin contact with wood dust are not fully known, and may | |
| | vary from one wood to another. | |
| Inhalation: | Not available | |
| Carcinogenicity: | Not listed as a carcinogen. | |
| Other Pertinent: | N/A | |
| 12. ECOLOGICAL INFORMATION: | | |
| In consideration of production and use of the material we can assume that no significant environmental impact of air | | |
| or water will arise. All the constitutions of the termite treatment preservation Permethrin (only OS′Brace™ H2 Blue) | | |
| are listed in the Australian Invento | ry of Chemical Substances (AICS). | |
| 13. DISPOSAL CONSIDERATIONS: | | |
| Waste Disposal Methods: | Generally wood and wood products can be disposed of by incineration or in a | |
| | local landfill. However, it is the users responsibility to insure wastes are | |
| | disposed of in accordance with all valid laws. | |
| 14. TRANSPORT INFORMATION: | | |
| No special transport requirements | are considered necessary. | |
| 15. REGULATORY INFORMATION: | | |
| Marking after EEC directive: | not required | |
| national regulations: | Formaldehyde emission class - E1 according "DIBt-recommendation 100" from | |
| - | June 1994 | |
| Waste code: | 17202 / 17203 according to the LAGA waste catalogue | |
| | 170201/030103 according to the European waste catalogue | |
| 16. OTHER INFORMATION | | |
| Important note: | | |

Important note:

All information and data rely on the today's conditions of our knowledge and represent no warranty of characteristics. EGGER Holzwerkstoffe Wismar GmbH &. Co. KG does not take over a warranty, regarding the accuracy or the completeness of these information and data. EGGER Holzwerkstoffe Wismar GmbH &. Co. KG will not be liable for claims relating the use of these information and data, independently of whether these information and data could have been incompletely, inaccurately or otherwise misleading. Existing laws and regulations for storage and use of our products are to be considered by the user within own responsibility.