17 Sep 14 03:25p

SAFE WORK METHOD STATEMENT

Page 1 of 3

[aceli].	Mark Bartley Roofing	Project Name/No:	All Jobs
Company (PCBU):	Teran Barray		Cape Cod Australia Pty Ltd
Work Activity / Task:	METAL ROOFER	Principal Contractor:	
Prepared by:	Mark Bartley	Date: 17 - 9 - 14	
Flepared by:		Note: Sign off to be pro	vided at Tool Box talk
Signature:	my	Note: Sign on to so pri	

If there are any tasks that may be included by way of variation to the plans or an alternative approach to the set task. It is a requirement to carry out a specific Risk Assessment for the tasks.

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
	Access to site	Slips, trips, falls and	Site specific induction.	Cape Cod
1	Access to site	accessibility. • UV / weather exposure.	 All "workers" to read the General Construction Safety Plan signage and Risk Assessment form before entering site. 	Mark Bartley C
			 Tool box talk to highlight any WHS concerns relative to the site. 	Mark Bartley
			 Ensure that the site and work place access is unobstructed. 	Mark Bartley C
			 Ensure all weather access to work areas. Provision of designated waste 	Cape Cod R
			 Storage of materials in designated areas. 	Cape Cod
			 Provide and maintain barricades to all materials stored on footpath and on site. 	Cape Cod S
	1		Regular site clean ups.	Mark Bartley
2	Unloading plant, equipment and	 Manual handling injuries. 	 Team lifting and carrying. Training of "workers" in correct 	Mark Bartley
	tools	 Slips, trips and falls. Proximity of other "workers". Public access. 	t mothods	
3	Setting up	Manual handling	 Set up in a clear area and maintain a clear travel path. 	Mark Bartley
	equipment	injuriesSlips, trips and falls	s "kare" in setting	Mark Bartley.

Reviewed by:

Gary Klomp

Principal Contractor's Representative

Construction Manager

Position

Date

Signature

SAFE WORK METHOD STATEMENT [cont.]

Page 2 of 3

	Job Step	Potential Hazard	Controls	Responsible Person/s
Item	јов жер	 Proximity of other "workers". Public access. 	up of electrical leads, power tools and nail guns. Ensure the proper use of all safety guards provided. Ensure that all electrical equipment and electrical leads have current tagging.	Mark Bartley C Mark Bartley C Mark Bartley C
4	Set out and install roof battens. Cut and fix foil backed insulation. Install metal sheet roofing	 Slips, trips, falls and accessibility. UV / weather exposure. Fall from height. Manual handling injuries. Sprains and strains. 	 Assess the site conditions including the weather and conduct a Risk Assessment before commencing. Provide "Restricted Access" warning signage. Establish a "No access area" below overhead work areas by barricading to prevent access to 	Mark Bartley Cape Cod Mark Bartley
		 Cuts and abrasions. Electrocution. Exposure to noise. Proximity of other "workers". Public access. 	the area of work. Provide a spotter where necessary. Identify that the electrical service has been isolated and that 'tiger tails' are in place as protection from overhead wires and points of attachment before commencing installation work.	Cape Cod &
			 Ensure that the guard rails to the ramp are in place and that the surface of ramp is clean before commencing. Ensure that the perimeter protection is in place [scaffoldin and edge protection] before 	S Continue C
			 Ensure that all openings and voids in the floor platform beloware covered. Check access ladder for damage defects before commencing use 	e/ Nack Bartley C
1			 Ensure that the access ladder is stable and secured top and bottom before use. Training of "workers" in safe working at heights and safe 	Mark Bartley Mark Bartley

Reviewed by:

Gary Klomp

Principal Contractor's Representative

Signature

Construction Manager

Position

Date

SAFE WORK METHOD STATEMENT [cont]

Page 3 of 3

p.8

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
			 movement on roof. Limit truss / rafter spacing to 600mm. 	Cape Cod
			Training of "workers" in correct lifting and carrying methods.	Mark Bartley
			Team lifting and carrying.	Mark Bartley
			 Ensure correct lifting and carrying techniques are used at all times. 	Mark Bartley
			 Rotate "workers" and vary tasks performed. 	Mark Bartley C
			 Wear appropriated PPE - hat, long sleeves, sun screen, sunglasses and fluids and reduce exposure where possible. 	Mark Bartley
			 Ensure "workers" have safety glasses, noise protection, appropriate protective footwear and gloves. 	Mark Bartley C
			 Training of "workers" in the safe use of power tools and nail guns. 	Mark Bartley
			 Ensure that all power tools have working safety guards. 	Mark Bartley
			 Provide MSDS for hazardous substances – insulation fibres. 	Cape Cod S
			 Provide appropriate containment and disposal of waste insulation. 	Cape Cod
			 Training of "workers" in the safe handling and use of insulation. 	Mark Bartley C
			 Storage of materials in designated areas. 	Cape Cod C
			 Maintain a clean and tidy work area. 	Mark Bartley

Reviewed	by:
----------	-----

Gary Klomp

Principal Contractor's Representative

Construction Manager

Position

Signature