Company [PCBU]:	TC Building Removal	Project Name/No:	All Jobs
Work Activity / Task:	CONCRETOR	Principal Contractor:	Cape Cod Australia Pty Ltd
Prepared by:	Todd Catto	Date: 20.4.15	
Signature:	T Cutto	Note: Sign off to be provided at Tool Box talk	

Note: Review of Control Measures -

If there are any tasks that may be included by way of variation to the plans or an alternative approach to the set task. It is a requirement to carry out a specific Risk Assessment for the tasks.

Task/Problem	Hazard	Like	lihoo	R	esu	lt		Possible Control	Action By	Date
Variation to plan	Unknown		d				rity	Tool Box Talk	Contractor	
Change of Brief			<u>~</u> <u></u>		a)		Priority	Work Method	Supervisor	}
		Likely	Possible Unlikely	Major	Severe	Minor		Statement		
		٧		٧			1			

						·				

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
1	Access to site	 Slips, trips, falls and accessibility. UV / weather exposure. 	 Site specific induction. All "workers" to read the General Construction Safety Plan signage and Risk Assessment form before entering site. 	Cape Cod Contractor
			 Tool box talk to highlight any OHS concerns relative to the site. 	Contractor
			Ensure that the site and work place access is unobstructed.	Contractor
			 Ensure all weather access to work areas. 	Cape Cod

Reviewed by:	Gary Klomp	Construction Manager
	On behalf of Cape Cod	Position,
		ſ
		17/10
	Signature	Date

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
			 Provision of designated waste areas. 	Cape Cod
			Regular site clean ups.	Contractor
2	Unloading of equipment and materials	Manual handling injuries.Slips, trips and falls.	 Assess Pedestrian / Traffic impact and develop traffic management plan, signage, barriers, witches hats. 	Contractor
		• Proximity of other "workers".	Team lifting and carrying.	Contractor
		Public access.	 Training of "workers" in correct lifting and carrying methods. 	Contractor
			 Unload and move the equipment and materials to a designated area to keep the footpath / work place access clear. 	Contractor
3	Setting up equipment	 Manual handling injuries. Slips, trips and falls. Proximity of other 	 Assess Pedestrian / Traffic impact and develop traffic management plan, signage, barriers, witches hats. 	Contractor
		"workers". • Public access.	 Set up in a clear area and maintain a clear travel path. 	Contractor
- SERVANIA AND AND AND AND AND AND AND AND AND AN		, abile decess.	 Training of "workers" in the setting up for concrete truck discharge, pump lines, plant and equipment. 	Contractor
T A VA		:	 Ensure the safety guards are provided to plant and equipment and that all plant and equipment is regularly maintained. 	Contractor
**************************************			Ensure that all electrical equipment is current tagging.	Contractor
			 Ensure that electrical equipment is attached to a residual current device [RCD]. 	Contractor
4	Preparing for concrete placement	Slips, trips and falls.UV / weather	Assess the site conditions and conduct a Risk Assessment before commencing.	Contractor

Reviewed by:	Gary Klomp
	On behalf of Cape Cod
	b
	Signature

Construction Manager

Position

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
		exposure. • Electrocution. • Hazardous substances.	Assess Pedestrian / Traffic impact and develop traffic management plan, signage, barriers, witches hats.	Contractor
STATEMENT AND ADDRESS OF THE PARTY OF THE PA		 Exposure to dust. Exposure to noise. Manual handling. Sprains and strains. Cuts and abrasions. 	 Identify that the electrical service has been isolated and that 'tiger tails' are in place as protection from overhead wires and points of attachment before commencing. 	Contractor
The second secon		• Proximity of other "workers".	Ensure that there is all weather access to the work place and that the access is unobstructed.	Contractor
		Public access.	Ensure all exposed tops of reinforcement starter bars are capped.	Contractor
, in the second			Establish a "No access area" round work areas by barricading to prevent access to the area of work.	Contractor
			Training of "workers" in setting up and safe use of pump lines, wheel barrows, mechanical trowelling machines, vibrators and plant and equipment.	Contractor
WAR THE			Wear appropriated PPE - hat, long sleeves, sun screen, sunglasses and fluids and reduce exposure where possible.	
· POPA MARKA MARKAMAN AND AND AND AND AND AND AND AND AND A			Use appropriate PPE – safety glasses, footwear, noise / hearing protection, dust protection [disposable], gloves and hard hat.	
angere de la companya			Training of "workers" in correct lifting and carrying methods.	
			Ensure correct lifting and carrying techniques are used at	

Reviewed by:	Gary Klomp
·	On behalf of Cape Cod

Signature

Construction Manager

Position

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
			 all times. Rotate "workers" and vary tasks performed. Hazardous substances –concrete, sand and cement, concrete curing compounds and additives. Training of "workers" in the safe handling and use of concrete, sand and cement, concrete curing compounds and additives Storage of materials in designated areas. Maintain a clean and tidy work area. Regular site clean ups. 	
5	Pour concrete - ground floor	 Slips, trips, falls and accessibility. UV / weather exposure. Electrocution. Hazardous substances. Exposure to dust. Exposure to noise. Manual handling. Proximity of other "workers". Public access. 	 Regular site clean ups. Assess the site conditions including the weather and conduct a Risk Assessment before commencing. Ensure that all exposed trenches are guard railed or covered. Ensure all exposed tops of reinforcement starter bars are capped. Ensure that work place access is unobstructed. Training of "workers" in safe use of plant and equipment. Training of "workers" in safe working over the placed reinforcement steel. Training of "workers" in correct lifting and carrying methods. Ensure that the correct lifting and carrying techniques are used at all times. 	

Reviewed by:	Gary Klomp
	On behalf of Cape Cod
	6
	Signature

Construction Manager

Position

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
			Systematic placement of concrete.	
			Rotate "workers" and vary tasks performed.	
. Trymponomer			 Provide MSDS for hazardous substances –cement, sand, concrete curing compounds and concrete mix additives. 	
140000			 Training of "workers" in the safe handling and use of concrete, sand and cement, concrete curing compounds and additives. 	
			Use appropriate PPE – safety glasses, footwear, dust protection [disposable], gloves.	
WHITE COLUMN TO THE COLUMN TO			 Storage of materials in designated areas. 	
			Maintain a clean and tidy work area.	
L Commission			Ensure waste is correctly disposed of.	

Reviewed by:	Gary Klomp	
	On behalf of Cape Cod	

Signature

Construction Manager
Position