SAFE WORK METHOD STATEMENT

Page 1 of 5

unapany merop	Mark Bartley Roofing	- Ргојест ман <i>истн</i> о:	A# 2005
Work Activity / Task:	ROOF TILER	Principal Contractor:	Cape Cod Australia Pty Ltd
Prepared by:	Mark Bartley	Date: 17-9-14	
	m Rod		

Note: Review of Control Measures -

If there are any tasks that may be included by way of variation to the plans or an alternative approach to the set task. It is a requirement to carry out a specific Risk Assessment for the tasks

ltem	Job Step	Potential Hazard	Controls	Responsible Person/s
1	Access to site	Slips, trips, falls and	Site specific induction.	Cape Cod
		UV / weather exposure.	 An Workers to must the Memoral Construction Safety Plan signage and Risk Assessment form before entering site. 	Mark Bartley C
			WHS concerns relative to the site.	INSTR BAITING C
			Fnsure that the site and work place scress is unabstructed.	Mark Bortley C
			 Ensure all weather access to work areas. 	Mark Bartley
			 Wear appropriated PPE - hat, long slooves, sun screen. 	Mark Bartley
		!	sengiasses and Hules and reciese exposure where possible.	S C-4 (2)
		1	 Regular site clean ups. 	Cape Cod
	:		Provision of designated waste	7: 7:: B
		:	 Storage of materials in designated areas. 	Cape Cod B
		1	Provide and maintain barricades	Cape Cod O
			footpath and on site.) AC
2	Unloading plant,	Manual handling	Team lifting and carrying.	Mark Bartley C
	roop edilibuseut and	injuries = Silps, trips and falls.	Training of "workers" in correct litting and carrying methods.	Mark Bartley C
		Proximity of other "workers". Public pages	Unload and move the equipment to designated area to keep footpath / work place access	Mark Bartley

Principal Contractor's Representative

A

Automatica est.

Position

176.2014

SAFE WORK METHOD STATEMENT [cont.]

Page 2 of 5

រំបែល 	අජාදී ප්රූ	Forential Hazard	Controls	Person/s
3	Setting up equipment	Manual handling injuries	Set up in a clear area and maintain a clear travel path.	Mark Bartley C
		 Proximity of other "workers". 	up of hoist / elevator, electrical leads, power tools and nail guns.	Mark Bartley
		Public access.	Ensure that all safety guards provided to plant and couloment are properly maintained and used.	Mark Bariley C
			Ensure that all electrical plant and equipment and leads have contain tagging.	Mar⊬ Bartley C
			 Ensure that all electrical plant and equipment are attached to a residual current device [RCD]. 	Mark Bartley C
	sunpping or existing roof covering	- Smps, trips, rails and accessibility. - UV / weather	- Assess the site conditions including the weather and conduct a Risk Assessment before commencing.	IMATE BATHLY &
	exposure. • Fairn Shiringing. • Hazardous	materials that <i>may</i> contain asbestos.	Mark Bardey S	
		materials.Identification of	Identify services and make sure that the electrical service has been isolated or safety relocated	Mark Bentley B
		Electrocution.Gas explosions.Falling objects.	 Use Licensed Electrician to isolate, disconnect and relate 	Cape Cod
		Exposure to dusc.Exposure to noise.Manual handling.	 Training of "workers" in safe working at heights and safe movement on roof. 	Mark Bartley
	ļ	e Simalia and shains.		5-7-5-7
		 Cuts and abrasions. Proximity of other "workers". Public access 	 and "Restricted Access" warning signage. Establish a "No access area" below everhead work areas by barricading to provent access to the area of work. Provide a 	Mark Bartley
			 spotter where necessary. Ensure that the scaffolding is 	Cape Cod &

ಗುರ್ಜಚಿಸುದರೆ ಅಳ್ಳ.

עמון אין אין אין

Principal Contractor's Representative

Signature

eonematical enembers

17 10, 2014

SAPE WORK INCINOUS STATEMENT (CORE.)

Page 3 of 5

tem	Job Step	Potential Hazard	Controls	Responsible Person/s
			safe and erected by a qualified Scaffolder.	B
			 Ensure that the perimeter protection is in place [scaffolding and edge protection; before commencing. 	Cape Cod
			Check access ladder for damage / defects before commencing use.	Mark Bartley
1			stable and secured top and bottom before use.	المالية
			Wear appropriated PPE - hat, wang standard stand	Mark Bartley C
			sunglasses and fluids and reduce exposure where possible.	
			Use appropriate PPE – safety glasses, footwear, noise / hearing test a salastics.	Mark Bartley
:			protection, dust protection [disposable], gloves and hard hats.	
			Systematic safe removal of	Cabo Cost
			Limit truss / rafter spacing to 600mm	Cape Cod
			Ensure that materials are not stored on spot or spotfold	Mark Sartley C
			 Provide a shute for materials into designated waste area. Provide a spotter where necessary. 	Cape Cod B
			designated waste areas	nametr Magnetour C
			Regular site clean ups.	Cape Cod S
5	Set out and installor batteria. Cut and fix sarking.	 Slips, trips, falls and accessionity. UV / weather exposure. 	Assess the site conditions Including the weather and conduct a Risk Assessment before commencing.	Mark Bartlev
f L	Load roof with	Fall from height Manual handling	e Identify that the electrical service has been isolated and that files talls' are in place as protection	Cabe Cod B
		injuries.	from overhead wires and points	

ಚಿತ್ರಗಲೆ ಕಾರಿಗೆ ಕಾರ್ತಿ	Principal Contractor's Representative	Position
	Signature	/ / Date

SAFE WORK METHOD STATEMENT (cont.)

Page 4 of 5

	\$_5_ F8.4-4	5_1_1_1_1_1_1_1_1_1_1_1_1_1_1_1_1_1_1_1		Responsible Person/s
	_ 10.00 10.00 -001	Public access	of attachment before commencing. Training of "workers" in the safe use and operation of ho-su elevator. Ensure operator ("worker") on ground wears a hard hat. Provide "nest reced necess warning signage. Establish a "No access area"	Mark Bartley Cape Cod Mark Bartley
			below overhead work areas by the area of work, Provide a spotter where necessary. Ensure that the guard rails to the range and in place and that the surface of ramp is clean before commencing. Ensure that the perimeter protection is in place [scaffolding and edge protection] before	Mark Bartley
			 Ensure that all openings and voids in the floor platform below the covered. Check access ladder for damage / 	Cape Cod S
			Check that the access ladder is while and secured top and bottom before use.	Mark Bartley Mark Bartley
			Training of "workers" in safe working at heights and safe movement on roof. Limit truss / rafter spacing to	Cape Cod B
			 Training of "workers" in correct lifting and carrying methods. 	Mark Bartley
:	!		 Ensure correct lifting and carrying techniques are used at all times. 	Mark Bartley C

		Construction Manager
Reviewed by:	Gary Klomp minimal contractor is nepresentative	<u></u> resition
		Data
	Signature	

SAFE WORK METHOD STATEMENT [cont.]

Page 5 of 5

Item	Job Step	Potential Hazard	Controls	responsible Person/s
		1	Rotate "workers" and vary tasks ranformed	Mark Bartley
			long sleeves, sun screen, sunglasses and fluids and reduce exposure where possible.	Wark bartley
			glasses, noise protection, appropriate protective footwear and gloves.	Mark Bartley
•	•	•	z rommini manazar megagine	
	1	İ	of power tools and nail guns.	
			 Ensure that all power tools have working safety guards. 	Mark Bartley
	! 		substances – silica, ilme, cement, sand and proprietary flexible pointing materials.	Midrik Sartiey B
			cement, sand and proprietary flexible pointing materials.	Mark Bartlev
			Storage of materials in cocionated gross	Mark Bartley C
			Maintain a clean and tidy work area.	Mark Bartley C
7	Site clean up on	Manual task injuries Lapusure to mis.	Remove any temporary hamitanday Mana Jangar appaired	Cape Cod & C
	work	Exposure to hazardous	 Place all rubbish/debris in designated storage area 	Mark Bartley C
		substances	Leave site/ work area in a clean Leave site/ work area in a clean	Mark Bartley

iicuicmen by:	Zair Addillis
	Principal Contractor's Representative
	Signature

التنبط والمتاور ويستبين بالمتاز تسيد Position