Company Name:	PAULICE CEMENT RENDERING PL	Project Name/No:	ALL SITES
Work Activity / Task:	POLYSTYRENE WALL CLADDING INSTALLATION	Principal Contractor:	Cape Cod Australia Pty. Ltd.
Prepared by:	PAUL FAMLUS	Date: 03-02-14	
Signature:	HES	Note: Sign off to be provided at Tool Box talk	

Note: Review of Control Measures - If there are any tasks that may be included by way of variation to the plans or an alternative approach to the set task, it is a requirement to carry out a "Specific Risk Assessment" for the tasks.

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
1	Access to site	<ul> <li>Slips, trips, falls and accessibility.</li> <li>UV light / weather exposure.</li> </ul>	<ul> <li>Site specific induction.</li> <li>All "workers" to register before entering the site; to read the General Construction Safety Plan signage; and to read the Site Specific Risk Assessment form.</li> </ul>	PF
			Tool box talk to highlight any WHS concerns relative to the site.	PF
			Ensure that the site and work place access is unobstructed.	C.C.
			Ensure all weather access to work areas.	دد
			<ul> <li>Provision of designated waste areas.</li> </ul>	CC
		november 1	Storage of materials in designated areas.	PF
			Provide and maintain barricades to all materials stored on footpath and on site.	CCLPF

Reviewed by: On behalf of Cape Cod

Constitution Mandie Position

Date

## SAFE WORK METHOD STATEMENT [cont.]

Page 2 of 3 v1.13

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
			Regular site clean ups.	
2	Unloading plant, equipment and tools	<ul> <li>Manual task injuries</li> <li>Slips, trips and falls.</li> <li>Proximity of other "workers".</li> <li>Public access.</li> </ul>	<ul> <li>Team lifting and carrying.</li> <li>Training of "workers" in correct lifting methods.</li> <li>Unload and move equipment to designated area to keep footpath / work place access clear.</li> </ul>	PF PF
3	Setting up equipment	<ul><li>Manual task injuries</li><li>Slips, trips and falls.</li></ul>	Set up in a clear area and maintain a clear travel path.	PF
		<ul> <li>Proximity of other "workers".</li> <li>Public access.</li> </ul>	Training of "workers" in setting up of electrical leads and power tools.	PF
			<ul> <li>Ensure the proper use of all safety guards provided.</li> </ul>	PF
			<ul> <li>Ensure that all electrical power tools and electrical leads have current tagging.</li> </ul>	PF
			Ensure that all power tools are attached to a residual current device [RCD].	PF
4	Carrying materials up ramp. Installation of	<ul> <li>Slips, trips, falls and accessibility.</li> <li>UV light / weather exposure.</li> </ul>	<ul> <li>Assess the site conditions including the weather and conduct a Site Specific Risk Assessment before commencing installation work.</li> </ul>	PF
	panel wall cladding	<ul> <li>Electrocution.</li> <li>Fall from height.</li> <li>Manual task injuries</li> <li>Exposure to dust.</li> </ul>	<ul> <li>Identify that the electrical service has been isolated and that 'tiger tails' are in place as protection from overhead wires and points of attachment before commencing installation work.</li> </ul>	PF/cc
	<ul> <li>Exposure to noise.</li> <li>Proximity of other "workers".</li> </ul>	<ul> <li>Wear appropriated PPE - hat, long sleeves, sun screen, sunglasses and fluids and reduce exposure where possible.</li> </ul>	PF	
		Public access.	<ul> <li>Ensure that the guard rails to the ramp are in place and that the surface of the ramp is clean before commencing.</li> </ul>	PFICL
:			<ul> <li>Ensure that scaffolding is safe and erected by a qualified Scaffolder before commencing.</li> </ul>	CC
			<ul> <li>Ensure that the perimeter protection is in place before commencing. [Scaffold as working platform]</li> </ul>	CC

Reviewed by: Gary Klome
On behalf of Cape Cod

## SAFE WORK METHOD STATEMENT [cont.]

Page 3 of 3 v1.13

Item	Job Step	Potential Hazard	Controls	Responsible Person/s
			Ensure that the edge protection to the roof surface [roof rail] and level work platforms are in place before commencing work from roof surface.	C.C./PF
			<ul> <li>Training of "workers" in safe working at heights and safe movement on roof.</li> </ul>	PF
			<ul> <li>Training of "workers" in correct lifting methods.</li> </ul>	PF
			Ensure that correct lifting and carrying techniques are used at all times.	PF
			Team lifting and carrying -limiting weights to manageable sizes.	PF
			<ul> <li>Ensure "workers" have safety glasses, noise protection, dust protection [disposable], protective footwear and gloves.</li> </ul>	PF
			Provide MSDS for hazardous substances - polystyrene.	PF
			Provide appropriate containment and disposal of waste polystyrene.	PF
			Training of "workers" in the safe handling and use of polystyrene.	PF
			Training of "workers" in the safe use of power tools.	PF
			Ensure all power tools have working safety guards.	PF
			Storage of materials in designated areas.	PF
			Maintain a clean and tidy work area.	PF/CC
5	Site clean up on completion of	Manual task injuries     Exposure to dust     Exposure to begandous	Remove any temporary barricades if no longer required	PF
work	•	<ul> <li>Exposure to hazardous substances-</li> </ul>	<ul> <li>Place all rubbish / debris in designated waste storage area</li> </ul>	PF
			Leave site / work area in a clean and tidy condition	PF

Reviewed by: 600 Composition On behalf of Cape Cod

E-Latham as per GK Signature