## ASBESTOS REGISTER



SITE: 7857 Ryan 26 Bundock Street, Randwick LAST UPDATED: 08/09/2017

JOB NUMBER CLIENT ADDRESS

Date Identified	Location of ACM	Туре	Friable / Non-Friable	Quantity	Condition	Assessment / Action
05/09/2017	Eave soffit lining	Asbestos cement sheet	Non-friable	20.5 sqm	Good/Stable Surface coated to the exposed areas	12 sqm to be removed by Cape Cod as part of the contract works. Protect the retained ACM from damage during the course of the works
05/09/2017	Skillion roof infill cladding	Asbestos cement sheet	Non-friable	1.5 sqm	Good/Stable Surface coated to the exposed areas	To be removed by Cape Cod as part of the contract works
05/09/2017	Laundry ceiling lining	Asbestos cement sheet	Non-friable	3.5 sqm	Good/Stable Surface coated to the exposed areas	To be removed by Cape Cod as part of the contract works
05/09/2017	Bathroom ceiling lining	Asbestos cement sheet	Non-friable	3.5 sqm	Good/Stable Surface coated to the exposed areas	To be removed by Cape Cod as part of the contract works
05/09/2017	Disused ceiling mounted hot water system	ACM	Non-friable	Unknown	Unknown	Remove and dispose of the disused hot water system with ACM

WHS-5.1-0502- Asbestos Register

Issued: February 2017

Version: 1.0

Page 1 of 2 Approved by: WHS & Human Resources Coordinator Printed: 8/09/2017 9:27 AM

## ASBESTOS REGISTER



05/09/2017	Electrical meter	ACM	Non-friable	0.25 sqm	Good/Stable	Protect the retained ACM from
	board					damage during the course of the
						works

WHS-5.1-0502— Asbestos Register

Issued: February 2017

Version: 1.0

Approved by: WHS & Human Resources Coordinator

Printed: 8/09/2017 9:27 AM