


ELEMENT STEP INSTRUCTIONS



STEP 1


Place right (A) and left (B) risers upright on a hard, flat surface. Insert center supports (C) into the slots in the left and right risers (see fig. 1). Press firmly until fully seated.

STEP 2

Place one tread (D) upside-down on a flat, smooth surface, narrow edge toward the back. Flip riser assembly and align top step area with tread. Riser holes should line up with tread holes in six places, two in each side, one front center, one back center. Install screws (E) through washer (F) into the holes (see fig. 2).

STEP 3

Place second tread (D) in the lower step area, narrow edge frontward so that tread and riser holes align (hold in place or rest lower step on a box or ledge). Install screws (E) and washers in five places, two in each side, one front center (see fig. 3)



ITEM	DESCRIPTION	QUANTITY
A	RIGHT RISER	1
B	LEFT RISER	1
C	CENTER RISER	5
D	TREAD	2
E	SCREW	11
F	WASHER	11

