

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Alfred St 33, North Melbourne
33 Alfred St North Melbourne
Contract No: P3430

Callouts:

Date of Call: 02-11-2018 17:30:00 Time of Arrival: 02-11-2018 17:50:00 Rectification Time: 02-11-2018 19:20:00 Time of Departure: 02-11-2018 20:10:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): O.O.O

For Lift(s): 2
For Floor(s): 1

Call Description: Lift 2 o.o.o

Order Number: .

DESCRIPTION OF WORK

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: Rope brake and govener tripped. Replaced fuse for rope brake. Reset govener and rope brake ran and tested ok

Part Required: No Parts Required

Service Technician Report Customer

Brad Stellini