

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Tarneit Railway
0 Cnr Leakes Rd & Derrumitt Rd Tarneit
Contract No: 3610

Callouts:

Date of Call: 06-11-2018 5:32:00 Time of Arrival: 06-11-2018 6:15:00 Rectification Time: 06-11-2018 6:25:00 Time of Departure: 06-11-2018 6:45:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): O.O.O

For Lift(s): 1

For Floor(s): g

Call Description: Ooo

Order Number:

DESCRIPTION OF WORK

Fault Found (CAUSE): Error Log Fault

Work Action (CORRECTION): See Work description

Work Description: Drive generated a hf26 error on start up\r\nError refers to internal soft start relay failing to close\r\nHardware fault 26 was able to be reset by powering down the drive\r\nFault cleared but if returns frequently would look towards repair or replacement

Part Required: No Parts Required

Service Technician

Report Customer

Matt Grieger