

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Leonard Crescent 26, Ascot Vale
26 Leonard Crescent Ascot Vale
Contract No: P3714

Callouts: 22486

Date of Call: 05-12-2018 11:22:23 Time of Arrival: 05-12-2018 12:03:00 Rectification Time: 05-12-2018 13:03:00 Time of Departure: 05-12-2018 13:16:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): Playing Up

For Lift(s): 1
For Floor(s): G

Call Description: lift says lift is too heavy and starts beeping

Order Number: #

DESCRIPTION OF WORK

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: Client advised that skmeone had been playing with security reader which when ever knocked would create an alarm inside car. Investigated potential issue and removed wires caught up in reader. Found module for load weigher getting caught on concrete ledge. Removed obsticle and returned lift to ser traced associated wiring for module to confirm good connection to control panel. Ran lift several times with no fault.

Part Required: No Parts Required

Service Technician Report Customer

Marek Torrico Client