

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Lonsdale St 103, Melbourne
103 Lonsdale St Melbourne
Contract No: P3290

Callouts: 22199

Date of Call: 05-11-2018 15:34:18 Time of Arrival: 05-11-2018 16:38:00 Rectification Time: 05-11-2018 17:38:00 Time of Departure: 05-11-2018 18:38:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): Button/Indicator Not Working

For Lift(s): 1

For Floor(s): G

Call Description: level 3 button has been pushed in and the panel has been pushed out

Order Number: #

DESCRIPTION OF WORK

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: Lift swing panel damaged.. re fixed clip and adjusted to fit.\r\nTemporarily fixed button for no 3 which was damaged

Part Required: No Parts Required

Service Technician Report Customer

Marek Torrico