

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:

Metro Ginifer station

0 St Albans Road Ginifer
Contract No: P3639

Callouts:

Date of Call: 23-11-2018 16:00:00 Time of Arrival: 23-11-2018 16:00:00 Rectification Time: 23-11-2018 21:00:00 Time of Departure: 23-11-2018 21:15:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): See Fault Description

For Lift(s): 1

For Floor(s):

Call Description: Meet metro worker regarding phone issue

Order Number:

DESCRIPTION OF WORK

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: After testing found that the problem was a broken wire in the flex shorting to earth dragging the signal down.\r\nSwap broken wire with spare flex\r\nTest all phones \r\nAll working

Part Required: No Parts Required

Service Technician

Report Customer

Matt Grieger