

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:

Batman's Hill on Collins
623 Collins Street Melbourne
Contract No: P3681

Callouts: 22143

Date of Call: 31-10-2018 11:38:50 Time of Arrival: 31-10-2018 13:15:00 Rectification Time: 31-10-2018 16:10:00 Time of Departure: 31-10-2018 16:20:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): Jerking

For Lift(s): 2

For Floor(s): .

Call Description: lift is shaking and there is a burning smell

Order Number: .

DESCRIPTION OF WORK

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: Car door operator fault replaced faulty belt tensioner roller on AMD door operator adjusted and checked operation ok.\r\nchecked motor roor equipment no burning smell detected.\r\nrelubricated car and counter weight guide rails checked operation ok.

Part Required: No Parts Required

Service Technician Report Customer

Robert Pelle Mark