

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Trak Centre
443 Toorak Rd Toorak
Contract No: P3166

Callouts: 22398

Date of Call: 26-11-2018 13:02:07 Time of Arrival: 26-11-2018 14:00:00 Rectification Time: 26-11-2018 14:45:00 Time of Departure: 26-11-2018 14:45:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): Noisy

For Lift(s): 1

For Floor(s): *

Call Description: Can hear loud noises from lift. Suspect problem with lift motor room - fan running computer is faulty

Order Number: *

DESCRIPTION OF WORK

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: Brake resistor enclosure ventilation fan faulty. Removed fan for replacement, secondary fan in operation.

Part Required: No Parts Required

Service Technician Report Customer

Nathan Downton Donna - 0412 366 615