

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:

William Angliss Institute (Building A - 555 La Trobe St) 555 La Trobe St Melbourne (Building A)

Contract No: P3175

Callouts: 22415

Date of Call: 27-11-2018 14:15:52 Time of Arrival: 28-11-2018 11:50:00 Rectification Time: 28-11-2018 13:25:00 Time of Departure: 28-11-2018 13:30:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): O.O.O

For Lift(s): 1

For Floor(s): ground floor

Call Description: lift is out of order

Order Number: .

DESCRIPTION OF WORK

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: error 36 brake fault \r\nfound faulty brake rectifier module board\r\nreplaced with new one checked operation, tested ok.

Part Required: No Parts Required

Service Technician Report Customer

Robert Pelle