

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Albert Redevelopment
140 Albert Road South Melbourne
Contract No: W3688

Callouts: 22145

Date of Call: 31-10-2018 12:07:26 Time of Arrival: 31-10-2018 3:50:00 Rectification Time: 01-11-2018 12:30:00 Time of Departure: 01-11-2018 13:35:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): Noisy

For Lift(s): 1

For Floor(s): .

Call Description: lift is noisy and not stopping at certain floors

Order Number: .

DESCRIPTION OF WORK

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: Broken inductor stack due to scissor lift racking car into inductor plates. Lift off for night. Back in morning with new inductors. Full shaft set floor levels and replaced inductors and plates.

Part Required: New inductors

Service Technician Report Customer

Brad Stellini