

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Trak Centre
443 Toorak Rd Toorak
Contract No: P3166

Callouts: 22412

Date of Call: 27-11-2018 12:42:23 Time of Arrival: 27-11-2018 13:10:00 Rectification Time: 27-11-2018 13:30:00 Time of Departure: 27-11-2018 13:40:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): Button/Indicator Not Working

For Lift(s): 2

For Floor(s): *

Call Description: push button in lift 2 is not working

Order Number: *

DESCRIPTION OF WORK

Fault Found (CAUSE): Button Broken

Work Action (CORRECTION): Replace/Repair Button

Work Description: Lift 2 level 2 button on panel faulty, replaced button, returned to service. Checked all other buttons in both passenger lifts. All working ok.

Part Required: No Parts Required

Service Technician Report Customer

Nathan Downton Donna - 0412 366 615