

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Pomeroy Pacific
15-19 Claremont St South Yarra
Contract No: P3295

Callouts: 22185

Date of Call: 05-11-2018 8:49:00 Time of Arrival: 05-11-2018 9:00:00 Rectification Time: 05-11-2018 9:10:00 Time of Departure: 05-11-2018 9:13:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): Button/Indicator Not Working

For Lift(s): 2

For Floor(s): 5

Call Description: level 5 button is pushed back into the compartment. metal ring is on level 5 at the reception desk

Order Number: *

DESCRIPTION OF WORK

Fault Found (CAUSE): Button Broken

Work Action (CORRECTION): Replace/Repair Button

Work Description: Lift 2 level 5 car call button surround broken. Replaced with new, returned to service.

Part Required: No Parts Required

Service Technician Report Customer

Nathan Downton Tom 0427 907 555