

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Glen Eira Sports & Aquatic Centre
200 East Boundary Road BENTLEIGH EAST
Contract No: P3399

Callouts: 22351

Date of Call: 20-11-2018 13:57:16 Time of Arrival: 20-11-2018 14:10:00 Rectification Time: 21-11-2018 14:30:00 Time of Departure: 21-11-2018 14:45:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): S.W.P

For Lift(s): 1

For Floor(s): G-1

Call Description: Person stuck in lift

Order Number: .

DESCRIPTION OF WORK

Fault Found (CAUSE): Door Operator Fault

Work Action (CORRECTION): See Work description

Work Description: Found lift on level G with SWP, pulled doors open to release passenger found broken door drive belt. Return 21/11 with new belt. Replace at test - ok.

Part Required: 3m fermator door drive belt

Service Technician Report Customer

Kevin Wilkins Jennifer 042 271 901