

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Little Saigon
61 Byron Street (32 Leeds St) Footscray
Contract No: 3736

Callouts: 22371

Date of Call: 23-11-2018 8:30:00 Time of Arrival: 23-11-2018 9:00:00 Rectification Time: 23-11-2018 13:30:00 Time of Departure: 23-11-2018 14:00:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): O.O.O

For Lift(s): 1

For Floor(s): 4

Call Description: lift is still playing up same as yesterday - PO53647

Order Number: 34216

DESCRIPTION OF WORK

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: E09 error \r\nLift needed to be placed onto inspection to clear fault\r\nMonitor brake switch operation on main board until it started raining a unable to work on lift controllers as open to the weather. Needs to be addressed.\r\n

Part Required: No Parts Required

Service Technician

Report Customer

Matt Grieger