

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Pomeroy Pacific
15-19 Claremont St South Yarra
Contract No: P3295

Callouts ID: 21982

Date of Call: 12-10-2018 12:57:21 Time of Arrival: 12-10-2018 13:30:00 Rectification Time: 12-10-2018 13:40:00 Time of Departure: 12-10-2018 13:46:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): Button/Indicator Not Working

For Lift(s): 2

For Floor(s): *

Call Description: Ground button is not working properly. When someone is on the 4th floor and presses G - does not go to ground floor

Order Number: *

DESCRIPTION OF WORK

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: Ground floor car call button surround broken, replaced with new button. Returned to service.

Part Required: Hunter D2AN-ANL254 button

Service Technician Report Customer

Nathan Downton Tamara 88256777