

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Victoria Hotel
215 Lt Collins St Melbourne
Contract No: P3234

Callouts: 22721

Date of Call: 27-12-2018 16:21:48 Time of Arrival: 27-12-2018 16:40:00 Rectification Time: 28-12-2018 16:50:00 Time of Departure: 27-12-2018 17:15:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): S.W.P

For Lift(s): 5

For Floor(s): 2

Call Description: SWP

Order Number: .

DESCRIPTION OF WORK

Fault Found (CAUSE): Door Lock Faulty

Work Action (CORRECTION): Replace Door/Lock Component

Work Description: 2nd floor door lock roller disengaged preventing doors from opening

Part Required: No Parts Required

Service Technician Report Customer

Graeme Gathercole