

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:

Maroodah Sports Club

O Cnr Dublin & Mt Dandenong Roads Ringwood East
Contract No: B3692

Callouts: 22461

Date of Call: 03-12-2018 9:51:33 Time of Arrival: 03-12-2018 11:00:00 Rectification Time: 03-12-2018 11:50:00 Time of Departure: 03-12-2018 12:30:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): O.O.O

For Lift(s): 1

For Floor(s): 1

Call Description: Lift display is flashing with \'0\'.\r\n\r\nReported by: Jim 0418 365 475\r\nLift stopped mid shaft

0

Order Number: 0

DESCRIPTION OF WORK

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: Lift had drive error 56 speed error.\r\nChanged parameter in drive in relation to speed monitoring and ran and tested lift.\r\nIf fault occurs agfurther investigation with second person will be required (mrl low head room)

Part Required: No Parts Required

Service Technician Report Customer

Zane Tregurtha