

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Keilor Rd 76-78, Essendon North
76-78 Keilor Rd Essendon North
Contract No: B3452

Callouts: 22421

Date of Call: 28-11-2018 10:29:18 Time of Arrival: 28-11-2018 13:00:00 Rectification Time: 28-11-2018 15:00:00 Time of Departure: 28-11-2018 16:00:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): Button/Indicator Not Working

For Lift(s): 1

For Floor(s): .

Call Description: security feature is not working, on one side their is a panel which does not require fob to be used to move to different levels? this is the panel wis not working

Order Number: 1411187336

DESCRIPTION OF WORK

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: Repair COP wiring and test operation of security overlay. All working after repair.

Part Required: No Parts Required

Service Technician Report Customer

mat tehan Chanelle 0386791300