

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Tanner St 28, Richmond
28 Tanner St Richmond
Contract No: P3529

Callouts: 22390

Date of Call: 26-11-2018 9:43:00 Time of Arrival: 26-11-2018 11:50:00 Rectification Time: 26-11-2018 12:25:00 Time of Departure: 26-11-2018 12:25:00

## CALLOUTS DETAILS

Reported Fault (COMPLAINT): Button/Indicator Not Working

For Lift(s): 1

For Floor(s): \*

Call Description: all landing panel lights are very dim on every floor

Order Number: \*

## **DESCRIPTION OF WORK**

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: Indicators didnt reboot properly after loss of mains power, reset indicators individually. Returned to service. Tested ok.

Part Required: No Parts Required

Service Technician Report Customer

Nathan Downton Kevin Charles 0419524597